

# Anamosa Dillion Military (Cemetery) Road Bridge Anamosa, Iowa




## 2024 Bridge Inspection Report

Bridge Inspection By: Modjeski and Masters, Inc.

Bridge Inspection Report By: Michael S. Januszkiewicz, P.E. and Shane D. Stauffer

June 30, 2024



*David Petermeier*  
Expires 12/31/25

## **Bridge Inspection Summary**

An inspection of the Anamosa Dillion Military (Cemetery) Road Bridge over the Wapsipinicon River located in Anamosa, IA was performed by Modjeski and Masters, Inc. (MM) under contract with the City of Anamosa as a subconsultant to HR Green, Inc. The inspection field work was performed from May 21 to May 24, 2024 by Messrs. M.S. Januszkiewicz, P.E. and S.D. Stauffer. Mr. D.W. Petermeier, P.E., S.E. was available for consultation during the field work, as well as report preparation. The inspection included a condition inspection of the overall structure to document structural defects, the collection of dimensions and details for the structure sufficient to perform potential subsequent load capacity ratings, and the performance of non-destructive ultrasonic testing (UT) of the truss bridge pins. The inspection was performed utilizing standard walking access, fall arrest access, and technical access climbing.

The bridge consists of a 167.5-foot single span pin connected Pratt truss supported by stone masonry abutments (see Photograph Nos. 1 thru 7 for typical structure photos). The bridge was previously utilized to convey pedestrian/bicycle traffic across the river; however, the bridge is currently closed to all traffic. The principal purpose of this inspection was to evaluate the structure for potential rehabilitation and reopening to pedestrian/bicycle traffic.

Existing plans and/or prior inspection reports for the structure were not available. For the purpose of this report, the bridge is orientated from south to north. The truss panel points / vertical members of the truss and floorbeams are numbered 0 through 10 increasing from south to north. The truss panels are numbered 1 through 10 from south to north (i.e., Panel Points 0 to 1 would equal Panel 1). The upper chord truss joints are designated with a U and the lower chord truss joints are designated with an L; thus, L5E is the lower chord truss joint at Panel Point 5 of the east truss line.

The following report includes a general discussion of the structure and its overall conditions, an itemized log of noted structural deficiencies, and a photograph log of overall conditions and representative deficiencies. Dimensional and detail sketches of the structure are included within Appendix A.

### **General Truss Findings:**

The top chords, end posts and verticals are built-up steel members, whereas the bottom chords, diagonals and lateral bracing members are pin connected eyebars. The truss members are in overall fair condition; however, the bridge pin connections are in poor condition (see the following section).

The truss metalwork typically exhibits paint failure with surface corrosion throughout. Crevice corrosion was observed throughout several top chord connection plates causing corrosion induced cracks. The bottom chord eyebars exhibit isolated areas of impact damage from apparent flood events. Several of the bridge pins exhibit surface cracks (U1W, L4W, U5W, U6W and L9E).

The upper and lower lateral bracing throughout is typically in satisfactory condition. The lower lateral bracing exhibits isolated areas of impact damage from apparent flood events.

The truss bearings are comprised of two fixed bearings at the North Abutment and two roller-type bearings at the South Abutment. The fixed bearings were not accessible due to dense vegetation.

The east roller retainer bar of the southeast roller bearing is displaced at the inboard and outboard ends allowing one roller to be completely displaced from the assembly and the remaining rollers to be misaligned. At the southwest roller bearing, the north roller is completely exposed and not bearing any load. The South Abutment bearings both have dirt and debris washed into the bearings.

#### Truss Bridge Pin Findings:

A detailed visual inspection of all 40 bridge pins was performed, as well as the UT inspection of 22 bridge pins. The UT inspection was conducted by Mr. M.S. Januszkiewicz, UT Level II. The UT inspection was conducted in accordance with the FHWA Guidelines for Ultrasonic Inspection of Bridge Pins and Modjeski and Masters' Ultrasonic Testing Procedure for the Inspection of Bridge Pins using the ultrasonic pulse-echo technique.

The UT inspection of the bridge pins was performed with the use of a GE/Krautkramer USM-Go portable ultrasonic flaw detector. The primary transducer used was a 0-degree 2.25 MHz, 0.50" diameter longitudinal wave transducer. Additional available transducers included a 2.25 MHz 0.50" diameter QC transducer and a 5.0 MHz, 0.50" diameter QC transducer with 45-degree, 12-degree, 5-degree and 20"-radius rocker wedges; and a 0-degree Krautkramer 5.0 MHz, 0.50" diameter longitudinal wave transducer.

The truss bridge pins are shouldered pins of various lengths (10" to 17" depending on location within the truss). Each pin face was cleaned with 60 and 80-grit sanding disks on a 4-1/2" angle grinder prior to UT inspection.

The bridge pin assemblies were initially visually inspected revealing the following:

- The bridge pins appear to be in good to satisfactory condition.
- Surface defects are apparent on the exposed end faces of all bridge pins (likely due to porosity and/or inclusions from the original fabrication of the bridge pins). Some of these surface defects are over 1/8" deep.
- Hammer marks and gouges exist in numerous pin faces but are difficult to distinguish from the porosity defects that are typical throughout.
- Fretting corrosion was not noted at any of the truss joints.
- All bridge pins appeared to be tight in their respective joints with no apparent movement or shifting of the pins within the joints.
- Once the paint was removed from the pin faces, visual cracks were revealed in five pins (U1W, L4W, U5W, U6W and L9E). These cracks are extremely tight with no fretting corrosion and they were not evident prior to removal of the paint. It seems likely that these cracks have existed for quite some time. Due to the fact that the paint was not cracked and that there isn't any fretting corrosion at the crack surfaces, these cracks appear to be inactive.

The UT inspection of the bridge pins revealed the following:

- There is an extreme amount of attenuation (dampening and scattering of sound due to a coarse grain microstructure and/or improper heat treatment processes employed during the formation of the bridge pins). The extreme amount of attenuation and the likely existence of numerous internal defects makes it impossible to ultrasonically "view" the entire volume of the various pins.
- Backwall measurements (pin lengths) could be identified for 21 of the 22 bridge pins examined with UT. Typically, backwall measurements could not be made throughout the

full circumference of each pin, but could be found from isolated locations on the various pin faces.

- Of the five bridge pins noted with visual cracks, a backwall signal could be found for each pin; thus, it appears that the visual cracks are likely isolated within a portion of the volume of each of the five pins.
- A-scans (UT machine screen shots) of a typical shouldered bridge pin versus the bridge pins of this structure with the extreme attenuation are included within Appendix B.

Although the bridge pins and their respective truss joints appear stable and tight with minimal wear or corrosion, there are five pins noted with visual cracks (U1W, U5W, U6W, L4W & L9E). Due to the nature of the extreme ultrasonic attenuation and the finding of five pins with visual cracks, the bridge pins are in poor condition. It is recommended that the bridge remain closed to any public traffic (pedestrian or otherwise).

#### General Floorsystem Findings:

The floorsystem consists of 13 timber stringers supported by timber end floorbeams at each abutment and steel built-up interior floorbeams throughout the span. The floorsystem is generally in satisfactory condition.

The timber stringers and end floorbeams typically exhibit minor checks and algae build-up. The timber floorbeams at each end are partially buried and can only be viewed from the face of the respective abutments. The exposed portions of each timber floorbeam appear to be intact with minor decay.

The steel built-up interior floorbeams connect to the truss vertical members via a square-stock U-bolt at each end of the floorbeam that is suspended from the lower chord bridge pin. The floorbeams exhibit paint failure with surface corrosion throughout with minimal section loss. There are isolated areas of crevice corrosion between the built-up plates/angles. The west end of several floorbeams exhibit impact damage from apparent flood events. The floorbeam-to-truss connections are in good condition; however, several of the spacer plates at the bottom of the floorbeam connections are cracked with portions missing.

#### General Deck Findings:

The deck consists of timber planking that is generally in fair condition with isolated areas in poor condition. Planks exhibit areas of checking, decay and advanced section loss throughout.

The bridge railing consists of steel chainlink fencing attached to the truss and floorsystem with welds and to the deck with U-shaped fasteners. The welds are located along the top rail and at the base of some railing posts. There are a total of 19 truss verticals, 1 truss diagonal eyebar, and 3 floorbeams with welded connections. Several of these welds are cracked, but none of the cracks appear to propagate into the base metal of the truss member or floorbeam.

#### General Substructure Findings:

The north and south abutments are constructed with stone masonry and are in overall poor condition. At the North Abutment, there is excessive vegetation and trees that prevented complete access. The North Abutment is missing mortar between all the masonry stones and there is one small 3" diameter tree growing from the mortar joint below the east truss line. The



South Abutment is also missing mortar between all of the masonry stones. At the interface between the west end of the South Abutment and the South Abutment's west wingwall, most of the masonry stones are partially displaced and a few large stones are missing. The South Abutment also exhibits minor vegetation growth, as well as evidence of previous plant debris and root systems throughout the abutment. Finally, the South Abutment may be susceptible to scour due to the flow of water and angle of attack being focused in this area; the presence of scour conditions could not be assessed during the inspection due to high flow of the river.

#### Conclusions and Recommendations:

A summary of the structure's overall conditions are as follows:

- Truss members – Fair
- Truss pins – Poor
- Truss expansion bearings – Poor
- Floorsystem – Satisfactory
- Deck – Fair (isolated Poor)
- Rail / Fence – Poor
- Substructure – Poor

The truss members, floorsystem and deck are in reasonable condition and could be rehabilitated for the continued use of the structure. However, the poor conditions of the truss pins and expansion bearings would require their replacement for continued use. The poor condition of the substructure would require extensive rehabilitation of the abutments (likely encasement) to extend their expected life. If the bridge were to be reopened for pedestrian access, the timber deck would likely require rehabilitation, if not replacement, and the existing rail / fence should be replaced with an appropriate pedestrian / bicycle railing system.

Due to the uncertainty of the internal conditions of the truss pins, the bridge should remain closed to public access.

Rehabilitation and/or replacement of the above noted components would be cost prohibitive and structure replacement is recommended.

**TABLE OF DEFICIENCIES**  
**Anamosa Dillion Military (Cemetery) Road Bridge**  
**May 24, 2024**

<b>Location(s)</b>	<b>Member(s)</b>	<b>Photo(s)</b>	<b>Deficiency(ies)</b>
U1W	Truss, Upper Pin	8	Crack in pin face
L4W	Truss, Lower Pin	9	Crack in pin face
U5W	Truss, Upper Pin	10	2 Cracks in pin face and surface pitting
U6W	Truss, Upper Pin	11	Crack in pin face
L9E	Truss, Lower Pin	12	Crack in pin face
L9W	Truss, Lower Pin	13	Typical pin face; surface deterioration
U4W	Truss, Top Chord Connection Plate		3/4" Crevice corrosion; one 2 1/4" corrosion induced crack
U6W	Truss, Top Chord Connection Plate		3/4" Crevice corrosion; 2 corrosion induced cracks on south side of plate, one 2" long and one 1 1/2" long
U7W	Truss, Top Chord Connection Plate		1 1/4" Crevice corrosion
U8W	Truss, Top Chord Connection Plate		1 1/4" Crevice corrosion
U4E	Truss, Top Chord Connection Plate	14	3/4" Crevice corrosion; 4 corrosion induced cracks - one 5 1/2" long crack and one 1" long crack on the north, and one 2 1/4" long crack and one 1" long crack on south side of plate
U6E	Truss, Top Chord Connection Plate		3/4" Crevice corrosion; 2 corrosion induced cracks on south side of plate; one crack 2 3/8" long and one crack 1 13/16" long
U8E	Truss, Top Chord Connection Plate		3/4" Crevice corrosion; 1 corrosion induced crack on south side of plate 1" long
U4E-U5E, Panel 5	Truss, Top Chord	15	3 1/4" long x 1/4" wide area of section loss
U1W-L1W	Truss, Vertical Eyebars	16	Northward deformation of vertical member by 2"
Panel 1 to Panel 5	Truss, West Bottom Chord Eyebars	17, 18	Downward and eastward deformation exhibited from impact damage
Panel 3	Truss, Lower Lateral Bracing	19	Impact damage; approximately 6" upward
Panel 4	Truss, Lower Lateral Bracing		Impact damage (deformation)
Panel 5	Truss, Lower Lateral Bracing	20	Impact damage; approximately 3" downward
L3W	Truss, Vertical Built-Up C-Channel	21	Flange angle sheared and bent for 4" from impact damage
L4W	Truss, Eyebars / Pin Assembly	22	1/4" Crevice corrosion typical of western lower pin assemblies

**TABLE OF DEFICIENCIES**  
**Anamosa Dillion Military (Cemetery) Road Bridge**  
**May 24, 2024**

<b>Location(s)</b>	<b>Member(s)</b>	<b>Photo(s)</b>	<b>Deficiency(ies)</b>
L4E, Panel 4	Truss, Bottom Chord	23	Log lodged between easternmost stringer and bottom chord at 4E Floorbeam
10E and 10W, Panel 10	Truss End Posts	1	Vegetation growth through Truss End Posts on both the east and west members
L2W	Floorbeam	24	Downward and northward deformation from impact damage
L2W	Floorbeam, Southwest Side - Top Flange	25	Impact damage (deformation)
L3W	Floorbeam, Southwest Flange	26	Sheared rivet from impact damage
L4W	Floorbeam, Southwest Side Flange	27	Eastward deformation from impact damage
L5W	Floorbeam, Southwest Side Flange	28	Sheared flange from impact damage
4W, Panel 5	Floorbeam, Web Connection Plate	29	3/4" Crevice corrosion; typical throughout
L4E	Floorbeam, East U-Bolt to Floorbeam Connection	30	Spacer plate cracked on south side of Floorbeam
L8W	Floorbeam, West U-Bolt to Floorbeam Connection	31	Spacer plate deterioration greater than 75%
1E, 9E, 9W	Fence Rail Post / Floorbeam	32	Fence rail post welded to floorbeam; cracked weld at 1E
0W-8W, 10W, 0E, 2E-8E, 10E	Top Fence Rail / Vertical Members	33, 34, 35	Top fence rail welded to vertical members
Panel 2	Deck	36	100% Section loss 1 1/2" long x 2" wide
South Abutment	East Roller Bearing	37	Roller retaining bar and roller displaced
South Abutment	West Roller Bearing	38	Roller exposed; not bearing load
South Abutment	West Wingwall	39	Missing stones from West Wingwall and South Abutment interface
South Abutment	North Face	40	Vegetation growth
North Abutment	West Wingwall	41	Vegetation growth
North Abutment	South Face	42	Vegetation growth



PHOTO 01

WEST ELEVATION



PHOTO 02

EAST ELEVATION



PHOTO 03

TYPICAL SECTION, LOOKING NORTH



PHOTO 04

UPPER TRUSS (PANELS 5-10), LOOKING NORTH





PHOTO 05

TYPICAL UPPER TRUSS JOINT (U7W)



PHOTO 06

TYPICAL LOWER TRUSS JOINT (L4W)





PHOTO 07 TYPICAL FLOOR SYSTEM (PANELS 9-10), LOOKING SOUTHEAST



PHOTO 08

U1W – TRUSS, UPPER PIN





PHOTO 09

L4W – TRUSS, LOWER PIN



PHOTO 10

U5W – TRUSS, UPPER PIN



PHOTO 11

U6W – TRUSS, UPPER PIN



PHOTO 12

L9E – TRUSS, LOWER PIN





PHOTO 13

L9W – TRUSS, LOWER PIN



PHOTO 14

U4E – TRUSS, TOP CHORD CONNECTION PLATE



PHOTO 15

U4E-U5E, PANEL 5 – TRUSS TOP CHORD



PHOTO 16

U1W-L1W – TRUSS, VERTICAL EYEBAR





PHOTO 17 PANEL 1 – TRUSS, WEST BOTTOM CHORD EYEBARS




PHOTO 18 PANELS 1-5 – TRUSS, WEST BOTTOM CHORD EYEBARS



PHOTO 19

PANEL 3 – TRUSS, LOWER LATERAL BRACING




PHOTO 20

PANEL 5 – TRUSS, LOWER LATERAL BRACING





PHOTO 21      L3W – TRUSS, VERTICAL BUILT-UP C-CHANNEL



PHOTO 22      L4W – TRUSS, EYEBAR / PIN ASSEMBLY





PHOTO 23

L4E, PANEL 4 – TRUSS, BOTTOM CHORD




PHOTO 24

L2W – FLOORBEAM



PHOTO 25      L2W – FLOORBEAM SOUTHWEST, TOP FLANGE




PHOTO 26      L3W – FLOORBEAM, SOUTHWEST FLANGE





PHOTO 27

L4W – FLOORBEAM, SOUTHWEST FLANGE



PHOTO 28

L5W – FLOORBEAM, SOUTHWEST FLANGE



PHOTO 29 4W, PANEL 5 – FLOORBEAM, WEB CONNECTION PLATE




PHOTO 30 L4E – FLOORBEAM, EAST U-BOLT SPACER PLATE





PHOTO 31 L8W – FLOORBEAM, WEST U-BOLT SPACER PLATE



PHOTO 32 1E – FLOORBEAM, RAILING POST



PHOTO 33

1W – FENCE RAILING



PHOTO 34

3E – FENCE RAILING





PHOTO 35

OW – FENCE RAILING



PHOTO 36

PANEL 2 - DECK





PHOTO 37 SOUTH ABUTMENT – EAST ROLLER BEARING



PHOTO 38 SOUTH ABUTMENT – WEST ROLLER BEARING





PHOTO 39

SOUTH ABUTMENT – WEST WINGWALL



PHOTO 40

SOUTH ABUTMENT





PHOTO 41

NORTH ABUTMENT – WEST WINGWALL



PHOTO 42

NORTH ABUTMENT

# Appendix A

## Structure Sketches

# North Abutment

10W

9W

8W

7W

6W Deck  
Measured 169'1"

5W

4W

3W

2W

1W

0W

10E

9E

8E

7E

6E

5E

4E

3E

2E

1E

0E

Bearing  
Seats  
Measured  
167.9'

16' 5 1/2"

16' 4 13/16"

16' 5 7/8"

16' 6 5/16"

16' 8 15/16"

16' 4 3/16"

Inner Web  
Face to Web Face Taken  
at Deck Level

South Abutment

# West Elevation






Photo 3W to 4W - Panel 4 Top Chord






Photo 3W Strut






# Vertical Members



	2W	3W	4W	5W
A.	8"	7 7/8"	6"	5"
B.	2"	2"	1 3/4"	1 9/16"
C.	12 5/16"	12 3/8"	11 3/4"	11 3/8"
D.	1 7/8"	1 7/8"	1 9/16"	1 3/8"
E.	8 5/16"	8 1/4"	8 3/16"	8 1/8"
F.	6 3/4"	6"	5"	4"
tw	.266	.206	.253	.187
CF	1/4"	1/4"	1/4"	1/4"

tw = UT Web Face For  
Web Thickness  
 CF = C-Channel Flange  
Thickness

# Vertical Lacing Bars & Rivet Detail / Spacing



A	$\approx 13\frac{1}{2}"$	All Verticals - Diagonal Lacing Bars
B	$\approx 15\frac{1}{2}"$	All Verticals - Vertical Lacing Bars
C	7"	Photo 2W 3 - Measurements Vary and Bottom Plate Placement Varies Based Off Vertical
D	3 $\frac{1}{8}"$	
E	10 $\frac{1}{2}"$	
Lacing Bars	3, 4, 5, 6, 7	Verticals 3-7 Lacing Bars 15" Long x 1 $\frac{1}{2}"$ Wide x $\frac{1}{4}"$ Thick
	2, 8	Verticals 2 & 8 Lacing Bars 15" Long x 1 $\frac{3}{4}"$ Wide x $\frac{1}{4}"$ Thick



### 10E to 9E Vertical Top Chord Connection




Photo 2W 4




Photo 9E Top Connection

Photo 3W - Top Chord Connection




Photo  
OW1

OW Diagonal Truss  
Member





Photo OW2







# IW I-Bar Pin Assembly - Vertical and Lower Horizontal

Photos 1W 1 & 1W 3

\* = 7/8" Thick






Photo  
 1W 2





No Vertical Measurement  
 Taken at 1W - Suspended  
 I-Bar

Vertical Measurements Taken  
 at 2W & 4W  
 From Bottom Edge of  
 Vertical to Bottom of  
 Top Chord









# Panel 2 - 2W Diagonal I-Bar




## 4W - Lower Horizontal I-Bar



## Lwr Horiz. I-Bar





# 3W Lateral Bracing to Pin Connection






# Photo 8E Floorbeam

Floorbeam Suspended From Vertical  
 Lower Pin/I-Bar Assembly  
 With U-Bolts



U-Bolt and  
 Center Connection  
 Plate Details  
 Not Obtained



Side  
 Profile




Top & Bottom Flanges Slotted For U-Bolt


## Appendix B

### UT A-Scans





**Figure B1:** Typical A-Scan (UT machine screen capture) of Shouldered Bridge Pin



**Figure B2:** Typical A-scan of Cemetery Road Bridge Pins (excessive attenuation blocking a thorough UT investigation of the volume of the pin).

Note: the pins shown in Figures B1 and B2 are of similar length and geometry.