

PHYSICAL NEEDS ASSESSMENT AND ENERGY AUDIT

HOUSING AUTHORITY OF BERGEN COUNTY

One Bergen County Plaza, Floor 2
Hackensack, New Jersey 07601
George Stavrou



PHYSICAL NEEDS ASSESSMENT AND ENERGY AUDIT of RIDGECREST APARTMENTS

7-11 Ridge Road
Ridgewood, New Jersey 07450

PREPARED BY:

EMG
222 Schilling Circle, Suite 275
Hunt Valley, Maryland 21031
800.733.0660
www.emgcorp.com

EMG CONTACT:

Edward Beeghly
Program Manager
800.733.0660, x7607
ebeeghly@emgcorp.com

EMG Project #: 107534.13R-009.308
Date of Report: August 7, 2014
On site Date: April 9, 2014

Replacement Reserves Report

Bergen-Ridgecrest Apartments-GPNA
5/10/2014



Report Section	ID	Cost Description	Lifespan (EUL)	E	Age	RUL	Quantity	Unit	Unit Cost	Subtotal	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	Deficiency Repair Estimate						
5.2	241179	G2022 Crack sealing and seal coating of the asphalt	5	3	2	4337	SY		\$3.56	\$15,440			\$15,440					\$15,440					\$15,440					\$15,440				\$61,759					
5.2	241180	G2025A Restripe parking lot	6	3	3	89	Stall		\$11.01	\$980				\$980						\$980					\$980							\$2,940					
6.3	241181	B3011 Asphalt shingles, removal and replacement with premium grade	30	19	11	415	SQ		\$430.00	\$178,450												\$178,450										\$178,450					
6.3	241182	B3011G Single Ply EPDM with insulation, fully adhered 45 mills, including demo	20	9	11	2	SQ		\$705.35	\$1,411												\$1,411										\$1,411					
6.8	241565	C3011 Paint and patch interior walls, drywall	7	3	4	35000	SF		\$0.84	\$29,400					\$29,400							\$29,400							\$29,400			\$88,200					
6.8	241192	C3024 Replace Vinyl tile	18	8	10	226	SY		\$67.75	\$15,312										\$15,312												\$15,312					
6.8	241191	C3025 Replace carpet, standard commercial, medium traffic	8	4	4	1605	SY		\$59.90	\$96,140					\$96,140								\$96,140									\$192,279					
6.8	241564	C3032 Replace acoustical ceiling tiles - partial	9	4	5	13	CSF		\$550.00	\$7,150						\$7,150									\$7,150							\$14,300					
6.8	241194	E1016 Replace commercial washers 30 lb	20	4	16	6	EA		\$12,420.00	\$74,520																	\$74,520					\$74,520					
6.8	241193	E1016 Coin operated dryer 30lb	15	4	11	6	EA		\$3,966.00	\$23,796												\$23,796										\$23,796					
6.8	241196	E1094 Refrigerator	15	6	9	1	EA		\$661.00	\$661										\$661												\$661					
6.8	241195	E1094 Range	20	6	14	1	EA		\$630.50	\$631															\$631							\$631					
7.1	244844	D3041 Gas-fired furnace 175 to 200 MBH with AC	25	20	5	1	EA		\$5,476.00	\$5,476						\$5,476																\$5,476					
7.1	241189	D3051 PTAC through the wall unit 1-ton	10	6	4	7	EA		\$1,401.00	\$9,807					\$9,807										\$9,807							\$19,614					
7.1	241187	D3052 Pad-Mounted Condenser 5-ton	15	2	13	1	EA		\$4,691.00	\$4,691														\$4,691								\$4,691					
7.1	241570	D3052 Replace duct heater (electric) 8.0kW	20	7	13	2	EA		\$1,551.00	\$3,102														\$3,102								\$3,102					
7.2	241200	D2023 Replace Amtrol Therm-x-trol	20	14	6	1	EA		\$2,200.00	\$2,200							\$2,200															\$2,200					
7.2	241199	D2023 Replace water storage tank 500 gallon	30	24	6	1	Each		\$4,369.00	\$4,369							\$4,369															\$4,369					
7.2	241198	D3021 Replace steam boiler, gas 1015 to 1275 MBH	35	29	6	1	EA		\$25,350.50	\$25,351							\$25,351															\$25,351					
7.4	240699	D5092 Replace Diesel Generator 150KW	25	8	17	1	EA		\$44,215.00	\$44,215																		\$44,215				\$44,215					
7.5	241201	D1011 Replace elevator hydraulic system, 2,500 lb capacity	20	17	3	2	Each		\$12,870.00	\$25,740				\$25,740																		\$25,740					
8.1	241571	C3011 Paint and patch interior walls, drywall	7	2	5	167680	SF		\$0.84	\$140,851						\$140,851						\$140,851								\$140,851		\$422,554					
8.1	241567	C3024 Replace Vinyl tile	18	12	6	1054	SY		\$67.75	\$71,409						\$71,409																\$71,409					
8.1	241566	C3025 Carpet, remove and replace in house	8	4	4	6350	SY		\$50.58	\$321,183					\$321,183								\$321,183									\$642,366					
8.2	241573	E1094 Refrigerator	15	8	7	130	EA		\$661.00	\$85,930								\$85,930														\$85,930					
8.2	241572	E1094 Range	20	11	9	130	EA		\$630.50	\$81,965										\$81,965												\$81,965					
8.3	244845	D3051 PTAC through the wall unit 1-ton	10	6	4	65	EA		\$1,401.00	\$91,065					\$91,065										\$91,065							\$182,130					
8.3	241574	D3051 PTAC through the wall unit 1-ton	10	2	8	65	EA		\$1,401.00	\$91,065									\$91,065										\$91,065			\$182,130					
8.4	241575	D2011 Replace Residential Grade water closet with 1.6 GPF unit	25	12	13	130	Each		\$447.00	\$58,110														\$58,110								\$58,110					
Totals, Unescalated											\$0	\$0	\$15,440	\$26,720	\$547,595	\$153,477	\$103,328	\$101,370	\$91,065	\$83,606	\$15,312	\$233,057	\$573,613	\$65,903	\$108,653	\$980	\$74,520	\$59,655	\$120,465	\$140,851	\$2,515,608						
Location Factor (1.00)											\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Totals, Escalated (3.0% inflation, compounded annually)											\$0	\$0	\$16,380	\$29,198	\$616,322	\$177,922	\$123,379	\$124,672	\$115,358	\$109,087	\$20,577	\$322,605	\$817,836	\$96,781	\$164,347	\$1,527	\$119,583	\$98,600	\$205,084	\$246,983	\$3,406,240						

TABLE OF CONTENTS

Certification	1
1. Executive Summary	3
1.1. Summary of Findings	3
1.2. Follow Up Recommendations.....	4
1.3. Opinions of Probable Cost.....	4
1.4. Methodology	4
2. Physical Needs Assessment - Purpose and Scope.....	6
2.1. Purpose	6
2.2. Deviations from the ASTM E2018-08 Guide	6
2.3. Additional Scope Considerations	7
2.4. Property's Remaining Useful Life Estimate	7
2.5. Personnel Interviewed	7
2.6. Documentation Reviewed	8
2.7. Pre-Survey Questionnaire	8
2.8. Weather Conditions.....	8
3. Code Information, Accessibility, and Mold	9
3.1. Code Information, Flood Zone and Seismic Zone	9
3.2. ADA Accessibility	9
3.3. Mold.....	10
4. Existing Building Evaluation	11
4.1. Apartment Unit Types and Unit Mix	11
4.2. Apartment Units Observed	11
5. Site Improvements	13
5.1. Utilities.....	13
5.2. Parking, Paving, and Sidewalks.....	13
5.3. Drainage Systems and Erosion Control.....	14
5.4. Topography and Landscaping	14
5.5. General Site Improvements.....	14
6. Building Architectural and Structural Systems	16
6.1. Foundations.....	16
6.2. Superstructure.....	16
6.3. Roofing.....	16
6.4. Exterior Walls	17
6.5. Exterior and Interior Stairs.....	17
6.6. Windows and Doors.....	18
6.7. Patio, Terrace, and Balcony	18
6.8. Common Areas, Entrances, and Corridors.....	18
7. Building Mechanical and Electrical Systems.....	20
7.1. Building Heating, Ventilating, and Air-conditioning (HVAC).....	20
7.2. Building Plumbing.....	20
7.3. Building Gas Distribution	21
7.4. Building Electrical.....	21
7.5. Building Elevators and Conveying Systems	22
7.6. Fire Protection Systems	22

8. Dwelling Units	24
8.1. Interior Finishes	24
8.2. Dwelling Appliances	24
8.3. HVAC.....	25
8.4. Plumbing	25
8.5. Electrical.....	26
8.6. Furniture, Fixtures and Equipment (FF&E)	26
9. Other Structures	27
10. Energy Audit - Purpose and Scope	28
11. Energy Conservation Measures.....	29
12. Utility Analysis	30
12.1. Electricity.....	31
12.2. Natural Gas	33
12.3. Water and Sewer	35
13. HUD Benchmarking	37
14. Recommended Operations and Maintenance Plan.....	39
15. Appendices.....	40

CERTIFICATION

EMG has completed a Physical Needs Assessment (PNA) and an Energy Audit of the subject property, Ridgecrest Apartments, located at 7-11 Ridge Road in Ridgewood, New Jersey. The PNA and Energy Audit were performed on April 9, 2014.

The PNA and Energy Audit were performed at the Housing Authority's request using methods and procedures consistent with good commercial and customary practice conforming to ASTM E2018-01, *Standard Guide for Property Condition Assessments: Baseline Property Condition Assessment Process*. Within this Physical Needs Assessment Report, EMG's follows the ASTM guide's definition of User, that is, the party that retains EMG for the preparation of a baseline PNA of the subject property. A User may include, without limitation, a purchaser, potential tenant, owner, existing or potential mortgagee, lender, or property manager of the subject property.

This report has been prepared for and is exclusively for the use and benefit of the Client identified on the cover page of this report. The purpose for which this report shall be used shall be limited to the use as stated in the contract between the client and EMG.

This report, or any of the information contained therein, is not for the use or benefit of, nor may it be relied upon by any other person or entity, for any purpose without the advance written consent of EMG. Any reuse or distribution without such consent shall be at the client's or recipient's sole risk, without liability to EMG.

The opinions EMG expresses in this report were formed utilizing the degree of skill and care ordinarily exercised by any prudent architect or engineer in the same community under similar circumstances. EMG assumes no responsibility or liability for the accuracy of information contained in this report which has been obtained from the Client or the Client's representatives, from other interested parties, or from the public domain. The conclusions presented represent EMG's professional judgment based on information obtained during the course of this assignment. EMG's evaluations, analyses and opinions are not representations regarding the building design or actual value of the property. Factual information regarding operations, conditions and test data provided by the Client or their representative has been assumed to be correct and complete. The conclusions presented are based on the data provided, observations made, and conditions that existed specifically on the date of the assessment.

EMG certifies that EMG has no undisclosed interest in the subject property, EMG's relationship with the Client is at arm's-length, and that EMG's employment and compensation are not contingent upon the findings or estimated costs to remedy any deficiencies due to deferred maintenance and any noted component or system replacements.

EMG's PNA cannot wholly eliminate the uncertainty regarding the presence of physical deficiencies and the performance of a subject property's building systems. Preparation of a PNA in accordance with Public Housing Modernization Standards Handbooks 7485.2 is intended to reduce, but not eliminate, the uncertainty regarding the potential for component or system failure and to reduce the potential that such component or system may not be initially observed. This PNA was prepared recognizing the inherent subjective nature of EMG's opinions as to such issues as workmanship, quality of original installation, and estimating the remaining useful life of any given component or system. It should be understood that EMG's suggested remedy may be determined under time constraints, formed without the aid of engineering calculations, testing, exploratory probing, the removal of materials, or design. Furthermore, there may be other alternate or more appropriate schemes or methods to remedy the physical deficiency. EMG's opinions are generally formed without detailed knowledge from individuals familiar with the component's or system's performance.

Any questions regarding this report should be directed to Edward Beeghly at ebeeghly@emgcorp.com or at 800.733.0660, x7607.

Prepared by: David Jacques, Field Observer

Reviewed by:



Solomon Rosenbaum, PE, CEM,
PNA Reviewer
For Edward Beeghly
Program Manager

1. EXECUTIVE SUMMARY

1.1. SUMMARY OF FINDINGS

The Housing Authority of Bergen County contracted with EMG to conduct a Physical Needs Assessment (PNA) and Energy Audit of the subject property, Ridgecrest Apartments, located at 7-11 Ridge Road in Ridgewood, Bergen County, New Jersey. The PNA was performed on April 9, 2014.

The multi-family property has two connected 3-story apartment buildings containing 130 apartment units. The building area is approximately 104,567 square feet. The site area is approximately 4.85 acres. Construction of the property was completed in 1984.

Summary of Physical Needs Assessment:

On site amenities include a community room, a library, and two laundry rooms.

Generally, the property appears to have been constructed within industry standards in force at the time of construction, to have been well maintained during recent years, and is in good overall condition.

According to property management personnel, the property has had a limited capital improvement expenditure program over the past three years, primarily consisting of repointing brick veneer and electric panel replacements in units. Supporting documentation was not provided, but some of the work is evident.

There are a number of Priority Deficiency Costs that have been identified during the evaluation period. These needs are identified in the various sections of this report and are summarized in the attached Replacement Reserves Report.

Summary of Energy Audit:

EMG has conducted an Energy Audit on the Ridgecrest Apartments. The study included a review of the building's construction features, historical energy and water consumption and costs, review of the building envelope, HVAC equipment, heat distribution systems, lighting, and the building's operational and maintenance practices.

EMG has identified eight Energy Conservation Measures (ECMs) for this property. The savings for each measure are calculated using standard engineering methods followed in the industry, and detailed calculations for ECM are provided in Appendix H for reference. A 10% discount in energy savings was applied to account for the interactive effects amongst the ECMs. In addition to the consideration of the interactive effects, EMG has applied a 15% contingency to the implementation costs to account for potential cost overruns during the implementation of the ECMs

Summary of Financial Information for Recommended Energy Conservation Measures

Item	Estimate
Total Projected Initial ECM Investment	\$ 426,860 (In Current Dollars)
Estimated Annual Cost Savings Related to ECMs	\$41,726 (In Current Dollars)
Net Effective ECM Payback	10.2 years

1.2. FOLLOW UP RECOMMENDATIONS

No additional evaluation is necessary.

1.3. OPINIONS OF PROBABLE COST

This section provides estimates for the repair and capital reserves items noted within this Physical Needs Assessment (PNA).

These estimates are based on invoice or bid documents provided either by the Owner/facility and construction costs developed from construction resources such as *R.S. Means* and *Marshall & Swift*, EMG's experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions.

1.4. METHODOLOGY

Physical Needs Assessment:

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, EMG opines as to when a system or component will most probably necessitate replacement. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its effective age. Projections of Remaining Useful Life (RUL) are based on continued use of the Property similar to the reported past use. Significant changes in tenants and/or usage may affect the service life of some systems or components.

The evaluation period identified in this report is defined as 20 years.

The physical condition of building component to be repaired is typically defined as being in one of five categories: Priority One through Five. For the purposes of this report, the following definitions are used:

Priority One - These items are to be addressed as Immediate. Items in this category require immediate action and include corrective measures to:

1. Correct life safety and/or code hazards
2. Repair item permitting water leaks into the building or structure
3. Repair mold or mildew conditions
4. Down unit repairs
5. Further study investigations

Priority Two - These items are to be addressed within the next 1 year. Items in this category require corrective measures to:

1. Return a system to normal operation
2. Stop deterioration to other systems
3. Stop accelerated deterioration
4. Replace items that have reached or exceeded their useful service life
5. ADA/UFAS deficiencies

Priority Three - These items are to be addressed within the next 2-3 years. Items in this category, if not corrected expeditiously, will become critical in the next several years. Items in this category include corrective measures to:

1. Stop intermittent interruptions
2. Correct rapid deterioration
3. Replace items that will reach or exceed their useful service life
4. Correct functionality and/or aesthetic issues that are not critical

Priority Four - These items are to be addressed within the next 3-5 years. Items in this category include conditions requiring appropriate attention to preclude predictable deterioration or potential downtime and the associated damage or higher costs if deferred further.

Priority Five - These items are to be addressed within 6-20 years. Items in this category represent a sensible improvement to the existing conditions. These are not required for the most basic function of the facility; however, Priority 5 projects will improve overall usability and/or reduce long-term maintenance costs.

Energy Audit:

All the ECMs are broken into two major categories:

1. **No/Low Cost Recommendations:** No/Low cost is defined as any project with initial investment of less than \$1000
2. **Capital Cost Recommendations:** Capital cost defined as any project with initial investment greater than \$1000

EMG screens ECMs based on the payback criteria.

Simple Payback Period –The number of years required for the cumulative value of energy or water cost savings less future non-fuel or non-water costs to equal the investment costs of the building energy or water system, without consideration of discount rates. ECMs with a payback period greater than the Expected Useful Life (EUL) of the project are not typically recommended, as the cost of the project will not be recovered during the lifespan of the equipment. These ECMs are recommended for implementation during future system replacement. At that time, replacement may be evaluated based on the premium cost of installing energy efficient equipment.

$$\text{Simple Payback} = \frac{\text{Initial Cost}}{\text{Annual Savings}}$$

2. PHYSICAL NEEDS ASSESSEMENT - PURPOSE AND SCOPE

2.1. PURPOSE

The purpose of this Physical Needs Assessment (PNA) is to assist the Client in evaluating the physical aspects of this property and how its condition may affect the soundness of the Client's financial decisions over time. For this PNA, representative samples of the major independent building components were observed and their physical conditions were evaluated. This included site and building exteriors, representative interior common areas, and a representative sample of the apartment units. Apartment unit observations include a minimum of 50 percent of the vacant units and all of the down units.

The property management staff and code enforcement agencies were interviewed for specific information relating to the physical property, code compliance, available maintenance procedures, available drawings, and other documentation. The property's systems and components were observed and evaluated for their present condition. EMG completed the *Systems and Conditions Table*, which lists the current physical condition and estimated remaining useful life of each system and component present on the property, as observed on the day of the site visit. The estimated costs for repairs and/or capital reserves are included in the enclosed cost tables. All findings relating to these opinions of probable costs are included in the narrative sections of this report.

The physical condition of building systems and related components are typically defined as being in one of three conditions: Good, Fair, or Poor, or a combination thereof. For the purposes of this report, the following definitions are used:

- Good = Satisfactory as-is. Requires only routine maintenance over the evaluation period. Repair or replacement may be required due to a system's estimated useful life.
- Fair = Satisfactory as-is. Repair or replacement is required due to current physical condition and/or estimated remaining useful life.
- Poor = Immediate repair, replacement, or significant maintenance is required.

2.2. DEVIATIONS FROM THE ASTM E2018-08 GUIDE

ASTM E2018-08, *Standard Guide for Property Condition Assessments: Baseline Property Condition Assessment Process* requires that any deviations from the Guide be so stated within the report. EMG's probable cost threshold limitation is reduced from the Guide's \$3,000 to \$2,000, thus allowing for a more comprehensive assessment on smaller scale properties. Therefore, EMG's opinions of probable costs that are individually less than a threshold amount of \$2,000 are omitted from this PNA. However, comments and estimated costs regarding identified deficiencies relating to life/safety or accessibility items are included regardless of this cost threshold.

In lieu of providing written record of communication forms, personnel interviewed from the facility and government agencies are identified in Section 2.5. Relevant information based on these interviews is included in Sections 2.5, 3.1, and other applicable report sections.

2.3. ADDITIONAL SCOPE CONSIDERATIONS

Items required by ASTM E2018-08 and Fannie Mae's *Exhibit III Specific Guidance to the Property Evaluator* are included within the Physical Needs Assessment (PNA). Additional "non-scope" considerations were addressed at the recommendation of EMG and subsequent contract with the Client. These additional items are identified as follows:

- Property disclosure information was obtained from the EMG's Pre-Survey Questionnaire
- An assessment of accessibility utilizing EMG's Accessibility Checklist.
- A limited visual assessment and review of the property for mold growth, conditions conducive to mold growth, and evidence of moisture in accessible areas of the property
- Provide a statement on the property's Remaining Useful Life
- Provide cross reference indexing between cost tables and report text
- Determination of FEMA Flood Plain Zone for single address properties

2.4. PROPERTY'S REMAINING USEFUL LIFE ESTIMATE

Subject to the qualifications stated in this paragraph and elsewhere in this report, the Remaining Useful Life (RUL) of the property is estimated to be not less than 35 years. The Remaining Useful Life estimate is an expression of a professional opinion and is not a guarantee or warranty, expressed or implied. This estimate is based upon the observed physical condition of the property at the time of EMG's visit and is subject to the possible effect of concealed conditions or the occurrence of extraordinary events such as natural disasters or other "acts of God" that may occur subsequent to the date of EMG's site visit.

The Remaining Useful Life for the property is further based on the assumption that: (a) the immediate repairs, short term repairs, and future repairs for which replacement reserve funds are recommended are completed in a timely and workman-like manner, and (b) a comprehensive program of preventive and remedial property maintenance is continuously implemented using an acceptable standard of care. The Remaining Useful Life estimate is made only with regard to the expected physical or structural integrity of the improvements on the property, and no opinion regarding economic or market conditions, the present or future appraised value of the property, or its present or future economic utility, is expressed by EMG.

2.5. PERSONNEL INTERVIEWED

The following personnel from the facility and government agencies were interviewed in the process of conducting the PNA:

Name and Title	Organization	Phone Number
Richard Goddin Property Manager	Housing Authority of Bergen County	201.954.4558
David Moody Housing Inspector Specialist	Bureau of Housing Inspection	609.633.6225

The PNA was performed with the assistance of Richard Goddin, Property Manager, The Housing Authority of Bergen County, the on site Point of Contact (POC), who was cooperative and provided information that appeared to be accurate based upon subsequent site observations. The on site contact is completely knowledgeable about the subject property and answered all questions posed during the interview process. The POC's management involvement at the property has been for the past 11 years.

2.6. DOCUMENTATION REVIEWED

Prior to the PNA, relevant documentation was requested that could aid in the knowledge of the subject property's physical improvements, extent and type of use, and/or assist in identifying material discrepancies between reported information and observed conditions. The review of submitted documents does not include comment on the accuracy of such documents or their preparation, methodology, or protocol. The following documents were provided for review while performing the PNA:

- Site plan
- Floor plan
- Utility bills
- Blueprints
- Pre-survey Questionnaire

No other documents were available for review. The Documentation Request Form is provided in Appendix E.

2.7. PRE-SURVEY QUESTIONNAIRE

A Pre-Survey Questionnaire was sent to the POC prior to the site visit. The questionnaire is included in Appendix E. Information obtained from the questionnaire has been used in preparation of this PNA.

2.8. WEATHER CONDITIONS

Weather conditions at the time of the site visit were clear, with temperatures in the 60s (°F) and light winds.

3. CODE INFORMATION, ACCESSIBILITY, AND MOLD

3.1. CODE INFORMATION, FLOOD ZONE AND SEISMIC ZONE

According to David Moody of the Bureau of Housing Inspection, there are no outstanding building code violations on file. The Building Department does not have an annual inspection program. They only inspect new construction, work that requires a building permit, and citizen complaints. A copy of the original Certificate of Occupancy was requested but was not available.

According to David Moody of the Bureau of Housing Inspection, there are no outstanding fire code violations on file. The most recent inspection was conducted by the Fire Department on May, 2013. The Fire Department inspects the property on an annual basis.

According to the Flood Insurance Rate Map, published by the Federal Emergency Management Agency (FEMA) and dated September 30, 2005, the property is located in Zone X (unshaded), defined as an area outside the 500-year flood plain with less than 0.2% annual probability of flooding. Annual Probability of Flooding of Less than one percent.

3.2. ADA ACCESSIBILITY

Section 504 of the Rehabilitation Act of 1973 is a Federal accessibility law that was enacted on June 2, 1988. Section 504 applies to multi-family properties that have 15 or more units. The property must have a minimum of five percent mobility accessible units and two percent of the units for visual/audio hearing impairments. Exceptions can be considered due to undue financial burdens or structural restrictions. However, the exceptions do not relieve the recipients from compliance utilizing other units/buildings or other methods to achieve reasonable accommodations.

Reasonable Accommodations as described in 24 CFR 8.4(b)(i), 8.24 and 8.33 are described as follows: When a family member requires an accessible feature(s) or policy modification to accommodate a disability, property owners must provide such feature(s) or policy modification unless doing so would result in a fundamental alteration in the nature of its program or result in a financial and administrative burden.

The Uniform Federal Accessibility Standard (UFAS) 24 CFR part 40 was adopted by HUD and made effective October 4, 1984. The UFAS applies only to new construction or to alterations to the existing buildings. Alterations are defined as work that costs 50 percent or more of the building's value when the work performed occurs within a twelve month period. Apartments modified for mobility impaired residents are to comply with UFAS.

Generally, Title III of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of "areas of public accommodations" on the basis of disability. Generally the rental office and access from the site to the rental office must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG). Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available; otherwise a reasonable accommodation must be made.

During the PNA, observations and sample measurements for accessibility were conducted. The scope of the observations is set forth in the EMG Accessibility Checklist provided in Appendix D. It is understood by the Client that the observations described herein does not comprise an Accessibility Compliance Survey of every unit and only those units where access was provided by the client were reviewed. Only a representative sample of areas were observed and, other than as shown on the accessibility checklist, actual measurements were not taken to verify compliance.

The accessibility standards that apply to the Property are Section 504, UFAS and where applicable, the ADA for access to the rental office. However, as the property is not new construction, or completing substantial rehabilitation or other rehabilitation, the property is only required to complete reasonable accommodations. Property management stated that Section 504 requests are completed on an individual case-by-case basis. Based on EMG's observations and interview of the Property Manager, the property is generally compliant with Section 504. Presently, approximately 9 percent of the units are defined as accessible for individuals with mobility impairments according to property management. There are four units at present which have visual/audio modifications, thus exceeding the two percent accessible requirements of Section 504.

Based on EMG's assessment, the property is in general compliance with the requirements of Section 504 and the ADA.

Based on EMG's assessment, no additional units should be made accessible to residents with mobility impairments and no units should be modified for residents who have visual/audio impairments.

Based on EMG's observations, the facility generally appeared to be accessible as stated within the defined priorities of Section 504, UFAS and the ADA.

3.3. MOLD

As part of the PNA, EMG completed a limited, visual assessment for the presence of visible mold growth, conditions conducive to mold growth, or evidence of moisture in readily accessible areas of the property. EMG interviewed property personnel concerning any known or suspected mold contamination, water infiltration, or mildew-like odor problems.

This assessment does not constitute a comprehensive mold survey of the property. The reported observations and conclusions are based solely on interviews with property personnel and conditions observed in readily accessible areas of the property at the time of the assessment. Sampling was not conducted as part of the assessment.

EMG did not note any visual indications of the presence of visible mold growth, conditions conducive to mold growth, or evidence of moisture in any readily accessible areas of the property.

4. EXISTING BUILDING EVALUATION

4.1. APARTMENT UNIT TYPES AND UNIT MIX

The gross area measurements in the chart below are an approximation, are based on information provided by on site personnel, and are not based on actual measurements. Due to the varying methods that could be utilized by others to derive square footage, the area calculations in the chart below do not warrant, represent, or guarantee the accuracy of the measurements.

Apartment Unit Types and Mix		
Quantity	Type	Floor Area
24	Studio	580 SF
105	1 Bedroom/1 Bathroom	540 SF
1	3 Bedrooms/1 Bathroom	830 SF
There is currently 1 vacant unit.		
There are currently 0 down units.		
130	TOTAL	

4.2. APARTMENT UNITS OBSERVED

Over twenty percent of the apartment units were observed in order to establish a representative sample and to gain a clear understanding of the property's overall condition. Other areas accessed included the exterior of the property, a representative sample of the roofs, and the interior common areas. The following apartments were observed.

Apartment Units Observed		
Unit/Floor	Type	Comments
2BN	1 Bedroom/1 Bathroom	Occupied. Good condition.
2EN	1 Bedroom/1 Bathroom	Occupied. Good condition.
2NN	Studio	Occupied. Good condition.
2RN	1 Bedroom/1 Bathroom	Occupied. Good condition.
2SN	1 Bedroom/1 Bathroom	Occupied. Good condition.
2DN	1 Bedroom/1 Bathroom	Occupied. Good condition.
2UN	1 Bedroom/1 Bathroom	Occupied. Good condition.
3AN	1 Bedroom/1 Bathroom	Occupied. Good condition.
3DN	1 Bedroom/1 Bathroom	Occupied. Good condition.
3EN	1 Bedroom/1 Bathroom	Occupied. Good condition.
3HN	1 Bedroom/1 Bathroom	Occupied. Good condition.
3JN	1 Bedroom/1 Bathroom	Occupied. Good condition.
3MN	Studio	Occupied. Good condition.

Apartment Units Observed		
Unit/Floor	Type	Comments
3RN	1 Bedroom/1 Bathroom	Occupied. Good condition.
3YN	1 Bedroom/1 Bathroom	Occupied. Good condition.
1DS	1 Bedroom/1 Bathroom	Occupied. Good condition.
1MS	Studio	Occupied. Good condition.
2AS	1 Bedroom/1 Bathroom	Occupied. Good condition.
2HS	1 Bedroom/1 Bathroom	Occupied. Good condition.
2JS	Studio	Occupied. Good condition.
2LS	Studio	Occupied. Good condition.
2OS	Studio	Occupied. Good condition.
2PS	1 Bedroom/1 Bathroom	Occupied. Good condition.
2RS	1 Bedroom/1 Bathroom	Occupied. Good condition.
2SS	1 Bedroom/1 Bathroom	Occupied. Good condition.
2TS	1 Bedroom/1 Bathroom	Occupied. Good condition.
3HS	1 Bedroom/1 Bathroom, ADA	Occupied. Good condition.
4FS	1 Bedroom/1 Bathroom	Occupied. Good condition.
4HS	1 Bedroom/1 Bathroom	Occupied. Good condition.
1FN	1 Bedroom/1 Bathroom, ADA	Occupied. Good condition.

All areas of the property were available for observation during the site visit.

A “down unit” is a term used to describe a non-rentable apartment unit due to poor conditions such as fire damage, water damage, missing appliances, damaged floor, wall or ceiling surfaces, or other significant deficiencies. According to the POC, there are no down units.

5. SITE IMPROVEMENTS

5.1. UTILITIES

The following table identifies the utility suppliers and the condition and adequacy of the services.

Site Utilities		
Utility	Supplier	Condition and Adequacy
Sanitary sewer	City of Ridgewood	Good and adequate
Storm sewer	Retention pond	Good and adequate
Domestic water	City of Ridgewood	Good and adequate
Electric service	PSEG	Good and adequate
Natural gas service	PSEG	Good and adequate

Observations/Comments:

- According to the POC, the utilities provided are adequate for the property. There is an emergency generator on site. Details of the generator are included in Section 7.4

5.2. PARKING, PAVING, AND SIDEWALKS

The main entrance drive is located along Ridge Road on the south side of the property. An additional entrance drive is located along Hillcrest road on the north side of the property. However, this road was temporarily closed off at the time of site inspection. The parking areas and drive aisles are paved with asphaltic concrete. The entrance driveway aprons are paved with asphaltic concrete.

Based on a physical count, parking is provided for 89 cars. The parking ratio is .68 spaces per apartment unit. All of the parking stalls are located in open lots. Five handicapped-accessible parking stalls are located adjacent to the main entrance, one of which is reserved for vans.

Type Space	Number of Spaces
Open Self Park	84
Handicapped-accessible	5
Total	89

The sidewalks throughout the property are constructed of cast-in-place concrete. Cast-in-place concrete steps with metal handrails are located at grade changes.

The curbs and gutters are constructed of cast-in-place concrete. Surface runoff is directed to swales along the drive aisles.

Observations/Comments:

- The asphalt pavement is in fair condition. There are no significant signs of cracks or surface deterioration. In order to maximize the pavement life, pothole patching, crack sealing, seal coating, and re-striping of the asphalt paving will be required over the assessment period. The cost of this work is included in the Replacement Reserves Report.
- The concrete pavement is in good condition. There are no significant signs of cracks or surface deterioration. Epoxy sealing of minor cracks will be required over the assessment period as part of the property management's routine maintenance program.
- The concrete curbs, gutters, and sidewalks throughout the property are in good condition. Routine cleaning and maintenance will be required over the assessment period.

5.3. DRAINAGE SYSTEMS AND EROSION CONTROL

Storm water from the roofs, landscaped areas, and paved areas flows into on site inlets and catch basins with underground piping connected to the retention pond.

Observations/Comments:

- There is no evidence of storm water runoff from adjacent properties. The storm water system appears to provide adequate runoff capacity. There is no evidence of major ponding or erosion.
- The retention pond appears to be in good condition and adequately sized for the property.

5.4. TOPOGRAPHY AND LANDSCAPING

The property slopes gently down from the west side of the property to the east property line.

The landscaping consists of trees, shrubs, and grasses. Flower beds are located throughout the site.

Surrounding properties include apartment buildings and residential houses.

Concrete masonry unit (CMU) retaining walls are located at grade changes throughout the site.

Observations/Comments:

- The topography and adjacent uses do not appear to present conditions detrimental to the property.
- The landscape materials are in good condition and will require routine maintenance over the assessment period.
- The retaining walls are in good condition. Routine maintenance will be required over the assessment period.

5.5. GENERAL SITE IMPROVEMENTS

Property identification is provided by a wood sign mounted on a post adjacent to the main entrance drive. Street address numbers are displayed on the exterior elevations.

Site lighting is provided by metal street light standards. The light standards are spaced along the drive aisles throughout the parking areas. Light fixtures mounted on metal poles are located along walkways and drive aisles throughout the property.

Exterior building illumination is provided by light fixtures surface-mounted on the exterior walls. A wall-mounted light fixture is located adjacent to each apartment unit's entrance door and patio or balcony door.

A perimeter fence is located along the east and west property lines. The fence is constructed of chain link with metal posts.

Dumpsters are located inside the trash rooms.

Observations/Comments:

- The property identification signs are in good condition. Routine maintenance will be required over the assessment period.
- The exterior site and building light fixtures are in good condition. Routine maintenance will be required over the assessment period.
- The site fencing is in good condition and will require routine maintenance over the assessment period. Painting is considered to be routine maintenance.
- The dumpsters are owned and maintained by the building owner. The dumpsters are in good condition and will require routine maintenance over the assessment period.

6. BUILDING ARCHITECTURAL AND STRUCTURAL SYSTEMS

6.1. FOUNDATIONS

Based on structures of similar size, configuration, and geographic location, it is assumed that the foundations consist of reinforced concrete slabs-on-grade with integral perimeter footings, interior footings, and column pad footings bearing directly on the soil.

Observations/Comments:

- The foundations and footings could not be directly observed during the site visit. There is no evidence of movement that would indicate excessive settlement.

6.2. SUPERSTRUCTURE

The building has concrete masonry unit (CMU) exterior and interior bearing walls, which support the upper floor and roof diaphragms. The upper floors are constructed of steel beams and topped with lightweight concrete. The roofs are sheathed with plywood over wood rafters and wood joists.

Observations/Comments:

- The superstructure is concealed. Walls and floors appear to be plumb, level, and stable. There are no significant signs of deflection or movement.

6.3. ROOFING

The primary roofs are classified as gabled roofs. The roofs are finished with asphalt shingles over asphalt-saturated paper. The roofs have sheet metal flashing elements. The roofs are insulated with fiberglass batts.

The roofs drain over the eaves to sheet metal gutters and downspouts, which are connected by underground piping to the storm drainage system.

The attics are ventilated by gable-end wall vents and soffit vents. The attics have draft stops. Attic access is provided by steps in the upper floor mechanical closet.

A small area of the roof is classified as a flat roof. The flat roofs are finished with an EPDM rubber membrane. The roofs are insulated with rigid insulation boards.

Storm water is drained from the roofs by gutters and downspouts which discharge to the underground storm drainage system.

There are no attics. The ceilings of the upper floor apartment units are the bottom side of the roof diaphragm.

Observations/Comments:

- The roof finishes are approximately nine years old. Information regarding roof warranties or bonds is not available. The roofs are maintained by an outside contractor.

- The fields of the roofs are in good condition. Based on the estimated Remaining Useful Life (RUL), the shingles will require replacement over the assessment period. The cost of this work is included in the Replacement Reserves Report.
- The fields of the roofs are in good condition. Based on the estimated Remaining Useful Life (RUL), the roof membranes will require replacement over the assessment period. The cost of this work is included in the Replacement Reserves Report.
- According to the POC, there are no active roof leaks. There is no evidence of active roof leaks.
- There is no evidence of roof deck or insulation deterioration. The roof substrate and insulation should be inspected during any future roof repair or replacement work.
- There is no evidence of fire retardant treated plywood (FRT) and, according to the POC, FRT plywood is not used.
- The roof flashings are in good condition and will require routine maintenance over the assessment period.
- Roof drainage appears to be adequate. Clearing and minor repair of drain system components should be performed regularly as part of the property management's routine maintenance program.
- The roof vents are in good condition and will require routine maintenance over the assessment period.
- There is no evidence of moisture, water intrusion, or excessive daylight in the attics. The insulation in the attics appears to be adequate.

6.4. EXTERIOR WALLS

The exterior walls are finished with brick masonry veneer. The soffits are exposed.

Building sealants (caulking) are located between dissimilar materials, at joints, and around window and door openings.

Observations/Comments:

- The exterior finishes are in good condition and will require routine maintenance over the assessment period.
- The sealant is flexible, smooth, and in good condition and will require routine maintenance over the assessment period.

6.5. EXTERIOR AND INTERIOR STAIRS

The interior stairs are constructed of steel and have closed risers and concrete-filled steel pan treads. The handrails and balusters are constructed of metal.

The exterior stairs are constructed of reinforced concrete. The handrails and balusters are constructed of metal.

Observations/Comments:

- The exterior and interior stairs, balusters, and handrails are in good condition and will require routine maintenance over the assessment period.

6.6. WINDOWS AND DOORS

The windows are vinyl-framed, double-glazed sliding units and have exterior screens.

The apartment unit entrance doors are painted metal doors set in wood frames. Exterior entrance doors to the apartments contain cylindrical locksets with lever handle hardware, security chains, keyed deadbolts, spy-eyes and door knockers.

Observations/Comments:

- According to the POC, the property does not experience a significant number of complaints regarding window leaks or window condensation. The windows are reported to be approximately 9 years old. There is no evidence of window leaks or condensation. The windows and screens are in good condition and will require routine maintenance over the assessment period.
- The exterior doors and door hardware are in good condition and will require routine maintenance over the assessment period.

6.7. PATIO, TERRACE, AND BALCONY

Not applicable. There are no patios, terraces, or balconies.

6.8. COMMON AREAS, ENTRANCES, AND CORRIDORS

The library/recreation room furnishings include sofas, chairs, tables, a television, electric fireplace, and wall decorations.

Community room furnishings include sofas, chairs, tables, a television, piano, television, and wall decorations. The common area kitchen is equipped with residential-style appliances, including a refrigerator, range, and microwave.

The lobby furnishings include sofas, chairs, tables, lamps, and wall decorations.

Apartment unit entrances are accessed from corridors beyond the lobby and from corridors on each floor.

Two common area restrooms are located near the main lobby.

Laundry rooms are located at the north and south side of the building. There are a total of six washing machines and six clothes dryers. A laundry sink is provided in each laundry room.

The following table identifies the interior common areas and generally describes the finishes in each common area.

Common Area	Floors	Walls	Ceilings
Lobby	Carpet	Painted drywall	Painted drywall
Library/Recreation room	Carpet	Painted drywall	Painted drywall
Corridor	Carpet	Painted drywall	Painted drywall
Laundry Room	Vinyl tile	Painted drywall	Suspend T-Bar with acoustic tiles
Common Area Kitchen	Vinyl tile	Painted drywall	Suspend T-Bar with acoustic tiles

Common Area	Floors	Walls	Ceilings
Common Area Restroom	Ceramic tile	Ceramic tile wainscots and Painted drywall	Painted drywall
Community room	Vinyl tile	Painted drywall	Painted drywall

Observations/Comments:

- The common areas were last renovated approximately seven years ago.
- The interior finishes in the common areas are in good condition. Based on the estimated Remaining Useful Life (RUL), the common area carpet and vinyl tile will require replacement during the assessment period. The cost of this work is included in the Replacement Reserves Report. Interior painting and wall finish replacement will also be required during the assessment period. The cost of this work is included in the Replacement Reserves Report. Based on the estimated Remaining Useful Life (RUL), the ceiling tiles will require replacement during the assessment period. The cost of this work is included in the Replacement Reserves Report.
- The common area kitchen appliances are in good condition. Based on the estimated Remaining Useful Life (RUL), some of the kitchen appliances will require replacement over the assessment period. The cost of this work is included in the Replacement Reserves Report.
- The washers and dryers are in good condition. Based on the estimated Remaining Useful Life (RUL), some of the washers and dryers will require replacement over the assessment period. The cost of this work is included in the Replacement Reserves Report.

7. BUILDING MECHANICAL AND ELECTRICAL SYSTEMS

7.1. BUILDING HEATING, VENTILATING, AND AIR-CONDITIONING (HVAC)

Heating and cooling are provided by packaged, terminal air-conditioning, (PTAC) units with integral thermostats. These units are throughout the common area rooms with two or three units in each area.

Cooling and heating in the community room is provided by a high-capacity, air handling unit, equipped with cooling coils and a heat pump furnace section. The air handling unit is located in a mechanical closet and is supplied by a pad-mounted condenser unit. The cooling equipment uses R-22 as a refrigerant.

Two electric duct heaters provide heat for the corridors and are located in the attic.

Natural ventilation is provided by operable windows. Mechanical ventilation is provided in the bathrooms by ceiling exhaust fans.

Observations/Comments:

- The property does not have a dedicated HVAC repair and maintenance contractor.
- Records of the installation, maintenance, upgrades, and replacement of the HVAC equipment have been maintained since the property was first occupied.
- The HVAC equipment varies in age. HVAC equipment is reportedly replaced on an "as-needed" basis.
- The PTAC units appears to be in fair to good condition. Based on their estimated Remaining Useful Life (RUL), the PTAC units will require replacement during the assessment period. The cost of this work is included in the Replacement Reserves Report.
- The air handler/furnace appears to be in fair condition. Based on its estimated Remaining Useful Life (RUL), the air handler will require replacement during the assessment period. The cost of this work is included in the Replacement Reserves Report.
- The condenser appears to be in good condition. Based on its estimated Remaining Useful Life (RUL), the condenser will require replacement during the assessment period. The cost of this work is included in the Replacement Reserves Report.
- The electric duct heaters appears to be in good condition. Based on its estimated Remaining Useful Life (RUL), the electric duct heaters will require replacement during the assessment period. The cost of this work is included in the Replacement Reserves Report.

7.2. BUILDING PLUMBING

The plumbing systems include the incoming water service, the cold water piping system, and the sanitary sewer and vent system. The risers and the horizontal distribution piping are copper. The soil and vent systems are PVC and cast iron.

The water meters are located in the utility room adjacent to compactor room #111 in the south-side building.

Domestic hot water is supplied by one gas-fired hydraulic boiler. The boiler has a rated input capacity of 1,202,000 BTUH and is located boiler room. The central hot water system consists of circulating pumps and a 500-gallon insulated storage tank.

The restrooms have commercial-grade fixtures and accessories including water closets and lavatories.

Observations/Comments:

- The plumbing systems appear to be well maintained and in good condition. The water pressure appears to be adequate. The plumbing systems will require routine maintenance during the assessment period.
- There is no evidence that the property uses polybutylene piping for the domestic water distribution system.
- The pressure and quantity of hot water appear to be adequate.
- The boiler appears to be in fair condition. Based on their estimated Remaining Useful Life (RUL), the boilers will require replacement during the assessment period. The cost of this work is included in the Replacement Reserves Report.
- The storage tank appear to be in fair condition. Based on their estimated Remaining Useful Life (RUL), the storage tank will require replacement during the assessment period. The cost of this work is included in the Replacement Reserves Report.
- The expansion tank appears to be in fair condition. Based on their estimated Remaining Useful Life (RUL), the expansion tank will require replacement during the assessment period. The cost of this work is included in the Replacement Reserves Report.
- The accessories and fixtures in the common area restrooms are in good condition and will require routine maintenance during the assessment period.

7.3. BUILDING GAS DISTRIBUTION

Gas service is supplied from the gas main on the adjacent public street. The gas meters and regulators are located in the gas meter room adjacent to the south building compactor room entrance. The gas distribution piping within the building is malleable steel (black iron).

Observations/Comments:

- The pressure and quantity of gas appear to be adequate.
- The gas meters and regulators appear to be in good condition and will require routine maintenance during the assessment period.
- Only limited observation of the gas distribution piping can be made due to hidden conditions. The gas piping appears to be in good condition.

7.4. BUILDING ELECTRICAL

The electrical supply lines run underground to a pad-mounted transformer, which feed interior-mounted electrical meters.

The main electrical service size is 3,000 amps, 120/208 volt three-phase four-wire alternating current (AC). The electrical wiring is copper, installed in metallic conduit sheathed cable. Circuit breaker panels are located throughout the building.

A diesel-powered 188 KVA emergency electrical generator is located at the east side of property. The generator provides back-up power for elements of the fire and life safety systems. The fuel tank is an above-ground tank located underneath the generator.

Observations/Comments:

- The on site electrical systems up to the meters are owned and maintained by the respective utility company.
- The electrical service and capacity appear to be adequate for the property's demands.
- The switchgear, circuit breaker panels, and electrical meters appear to be in good condition and will require routine maintenance during the assessment period.
- The generator is in good condition and is reportedly tested on a weekly basis. Based on its estimated Remaining Useful Life (RUL), the generator will require replacement during the assessment period. The cost of this work is included in the Replacement Reserves Report.

7.5. BUILDING ELEVATORS AND CONVEYING SYSTEMS

There are a total of two hydraulic passenger elevators. The elevators were manufactured by Dover. Each elevator has a rated capacity of 2,500 pounds and a speed of 100 fpm. The elevator machinery is located in a room adjacent to the shaft.

Each elevator cab has rubber floors, vinyl wall panels, and surface-mounted light fixtures. The doors are fitted with mechanical safety stops. Emergency communication equipment is provided in each cab.

Observations/Comments:

- According to the POC, the elevators, and their responsiveness, provide adequate service. The elevators are serviced by Clifton Elevator Company on a monthly basis. The elevator machinery and controls are the originally installed system. Based on the estimated Remaining Useful Life (RUL), some of the elevator equipment will require replacement over the assessment period. The cost of this work is included in the Replacement Reserves Report.
- The elevators are inspected on an annual basis by the municipality, and a certificate of inspection is displayed in the elevator cabs.
- According to the POC, the emergency communication equipment in the elevators is functional. Equipment testing is not within the scope of a Property Condition Assessment.
- The finishes in the elevator cabs appear to be in fair condition. Based on the estimated Remaining Useful Life (RUL), the cab finishes will require replacement over the assessment period. The cost to replace the finishes is relatively insignificant and the work can be performed as part of the property management's routine maintenance program. The cost of this work is not included in the cost tables.

7.6. FIRE PROTECTION SYSTEMS

The fire protection systems consist of a wet-pipe sprinkler system for the common areas, a wet standpipe with fire department hose valves and connections in each stair tower, portable fire extinguishers, smoke detectors, pull stations, and alarm horns. Hardwired smoke detectors are located throughout the common areas and in each apartment unit. The nearest fire hydrants are located along the property's drive aisles and are approximately 40 feet from the building.

Fire sprinkler risers are located in a fire protection equipment room, adjacent to the south building compactor room #111. The system is also equipped with backflow preventers.

Common areas and corridors are equipped with generator back up lights, illuminated exit signs, pull stations, alarm horns, and strobe light alarms.

A central fire alarm panel is located in the management office and monitors the pull stations, smoke detectors, and flow switches. The alarm panel also sounds the alarm and automatically notifies the monitoring service and the fire department in the event of trouble.

Observations/Comments:

- Information regarding fire department inspection information is included in Section 3.1.
- The fire extinguishers are serviced annually and appear to be in good condition. The fire extinguishers were serviced and inspected within the last year.
- The pull stations and alarm horns appear to be in good condition and will require routine maintenance over the assessment period.
- The pull stations and alarm horns appear to be in good condition. The alarm horns are not equipped with strobe lights. See Section 3.2. for comments and cost requirements regarding strobe light alarms.
- Smoke detector replacement is considered to be routine maintenance.
- Exit sign and emergency light replacement is considered to be routine maintenance.
- According to the POC, the central alarm panel is in good condition and is serviced regularly by a qualified fire equipment contractor. Equipment testing is not within the scope of a Property Condition Assessment.

8. DWELLING UNITS

8.1. INTERIOR FINISHES

The following table generally describes the interior finishes in the apartment units:

Typical Apartment Finishes			
Room	Floor	Walls	Ceiling
Living room	Carpet	Painted drywall	Painted drywall
Kitchen	Vinyl tile	Painted drywall	Painted drywall
Bedroom	Carpet	Painted drywall	Painted drywall
Bathroom	Ceramic tile	Ceramic tile tub wainscot and painted drywall	Painted drywall

The interior doors in each apartment unit are painted hollow-core wood doors set in wood frames. Wardrobe closets are accessed by bi-fold doors.

Observations/Comments:

- The residential units are typically renovated upon tenant turnover. The renovation generally consists of floor finish cleaning or replacement, interior painting, general cleaning, and repair or replacement of any damaged items.
- The interior finishes in the apartment units are in good condition. Based on the estimated Remaining Useful Life (RUL), the carpet and vinyl flooring will require replacement over the assessment period. The cost of this work is included in the Replacement Reserves Report.
- The interior painting in the apartment units are in good condition. Based on the estimated Remaining Useful Life (RUL), painting will be required over the assessment period. The cost of this work is included in the Replacement Reserves Report.
- The interior doors and door hardware are in good condition and will require routine maintenance.
- The closet doors are in fair condition and will require replacement and will require routine maintenance.

8.2. DWELLING APPLIANCES

Each apartment unit kitchen typically includes the following appliances:

Appliance	Comment
Refrigerator	Defrosting
Range	Electric
Hood	Ducted
Dishwasher	Not provided
Disposal	Not provided

The kitchen cabinets are constructed of wood. The countertops are wood and have a plastic-laminated finish.

Observations/Comments:

- According to the POC, apartment appliances are reportedly replaced on an "as needed" basis.
- The kitchen appliances appear to be in fair to good condition. Based on their estimated Remaining Useful Life (RUL), some of the kitchen appliances will require replacement over the assessment period. The cost of this work is included in the Replacement Reserves Report. As noted in the energy conservation section, replacement with Energy Star refrigerators should be performed.
- The kitchen cabinets vary in age and are in fair to good condition. Some cabinets will require refinishing or replacement over the assessment period. This work is considered to be routine maintenance.
- The kitchen countertops vary in age and are in fair to good condition. Some countertops will require refinishing or replacement over the assessment period. This work is considered to be routine maintenance.

8.3. HVAC

Heating and cooling is provided by packaged, terminal air-conditioning, (PTAC) units with integral thermostats. There is one unit in each room.

Natural ventilation is provided by operable windows. Mechanical ventilation is provided in the bathrooms by ceiling exhaust fans.

Observations/Comments:

- The HVAC systems are maintained by an outside contractor. Records of the installation, maintenance, upgrades, and replacement of the HVAC equipment at the property have been maintained since the property was first occupied.
- Upon review of the records provided and discussions HABC Maintenance and Engineering staff, the HVAC equipment varies in age. HVAC equipment is reportedly replaced on an "as needed" basis.
- The PTAC units appear to be in fair to good condition. Based on the estimated Remaining Useful Life (RUL), all of the PTAC units will require replacement over the assessment period. The cost of this work is included in the Replacement Reserves Report. As noted in the energy conservation section, energy efficient PTHP units should be considered when PTAC replacement is required.

8.4. PLUMBING

The bathrooms include a water closet, a enameled-steel bathtub, a vanity, and a lavatory.

Domestic hot water is supplied by the central system described in Section ☐

Observations/Comments:

- The bathroom fixtures are in good condition and will require minor replacements routine maintenance over the assessment period. Replacement of some of the fixtures as part of the energy conservation measures is recommended in Section 10.
- The bathtubs are in fair to good condition and will require routine maintenance.
- The water closets appear to be in fair to good condition. Based on the estimated Remaining Useful Life (RUL), all of the water closets will require replacement over the assessment period. The cost of this work is included in the Replacement Reserves Report.
- Although not tested, there is no indication through observations or discussions with staff and residents that the pressure and quantity of hot water are inadequate.

8.5. ELECTRICAL

The electrical service to each apartment unit is 125 amps. A circuit breaker panel inside each unit supplies the HVAC system, appliances, receptacles and light fixtures.

The apartment units have incandescent and fluorescent light fixtures. Each apartment unit has at least one cable television outlet and telephone jack.

Observations/Comments:

- The apartment unit light fixtures are in good condition. Light fixture replacement is considered to be routine maintenance.
- The current electrical system at the Project Site is in good overall condition and is adequately configured with regard to “provided” versus “demanded” electrical capacity for each apartment unit.
- As noted in the energy conservation portion of this report, replacement of light fixtures should include CFLs and T-8 lamps.

8.6. FURNITURE, FIXTURES AND EQUIPMENT (FF&E)

Not applicable. There are no furnished apartments.

9. OTHER STRUCTURES

A small storage building is located at the east side of building. The maintenance building is a pre-manufactured wood structure set on a concrete slab. Building has a stained wood siding and asphalt shingles

Observations/Comments:

- The shingles are in good condition. Based on the estimated Remaining Useful Life (RUL), the shingles will require replacement over the assessment period. The cost of this work is relatively minimal and should be performed as part of routine maintenance.
- The wood siding is in good condition. Based on the estimated Remaining Useful Life (RUL), the wood siding will require painting over the assessment period. The cost of this work is relatively minimal and should be performed as part of routine maintenance.

10. ENERGY AUDIT - PURPOSE AND SCOPE

The purpose of this Energy Audit is to provide Ridgecrest Apartments with a baseline of energy usage, the relative energy efficiency of the facility, and specific recommendations for Energy Conservation Measures. Information obtained from these analyses may be used to support a future application to an Energy Conservation Program, Federal and Utility grants towards energy conservation, as well as support performance contracting, justify a municipal bond-funded improvement program, or as a basis for replacement of equipment or systems

The energy audit consisted of an on site visual assessment to determine current conditions, itemize the energy consuming equipment (i.e. Boilers, Make-Up Air Units, DHW equipment); review lighting systems both exterior and interior; and review efficiency of all such equipment. The study also included interviews and consultation with operational and maintenance personnel. The following is a summary of the tasks and reporting that make up the Energy Audit portion of the report.

The following is a summary of the tasks and reporting that make up the Energy Audit portion of the report.

ENERGY AND WATER USING EQUIPMENT

- EMG has surveyed the common areas, maintenance facilities and mechanical rooms to document utility-related equipment, including heating systems, cooling systems, air handling systems and lighting systems.

BUILDING ENVELOPE

- EMG has reviewed the characteristics and conditions of the building envelope, checking insulation values and conditions. This review also includes an inspection of the condition of walls, windows, doors, roof areas, insulation and special use areas. Where we anticipated significant losses, we utilized infrared thermographs to analyze heat loss across the envelope.

RECOMMENDATIONS FOR ENERGY SAVINGS OPPORTUNITIES

- Based on the information gathered during the on site assessment, the utility rates, as well as recent consumption data and engineering analysis, EMG has identified opportunities to save energy and provide probable construction costs, projected energy/utility savings and provide a simple payback analysis.

ANALYSIS OF ENERGY CONSUMPTION

- Based on the information gathered during the on site assessment and a minimum of one year of utility billing history, EMG has conducted an analysis of the energy usage of all equipment, and identified which equipment is using the most energy and what equipment upgrades may be necessary. As a result, equipment upgrades or replacements are identified that may provide a reasonable return on the investment and improve maintenance reliability.

ENERGY AUDIT PROCESS

- Interviewing staff and review plans and past upgrades
- Performing an energy audit for each use type
- Performing a preliminary evaluation of the utility system
- Analyzing findings, utilizing ECM cost-benefit worksheets
- Making preliminary recommendations for system energy improvements and measures
- Estimating initial cost and changes in operating and maintenance costs based on implementation of energy efficiency measures
- Ranking recommended cost measures, based on the criticality of the project and the largest payback

11. ENERGY CONSERVATION MEASURES

EMG has identified eight Energy Conservation Measures (ECMs) for this property.

Priority	Brief description of ECM	Initial Investment	Annual Savings	Payback Period (yrs)	Component EUL (yrs)
1	Replace Incandescent Lighting with CFLs in Common Areas	\$114	\$1,034	0.1	5
2	Replace Incandescent Fixtures at Apartment Entry Lights with LED Wall Packs	\$910	\$770	1.2	5
3	Replace Older Refrigerators with Energy Star Rated Refrigerators	\$45,162	\$5,103	8.8	15
4	Replace Older Plumbing Fixtures with Low Flow Devices	\$51,870	\$5,198	10.0	20
5	Replace Inefficient Boilers -2070000 Btu/hr	\$41,400	\$3,839	10.8	25
6	Replace Older PTAC Units with PTHP Units	\$232,100	\$21,491	10.8	15
7	Replace Fluorescent Fixtures in Common Areas with T-8 Bulbs & Electronic Ballasts	\$13,104	\$1,167	11.2	15
8	Replace Newer PTAC Units with PTHP Units	\$42,200	\$3,122	13.5	15

12. UTILITY ANALYSIS

Establishing the energy baseline begins with an analysis of the utility cost and consumption of the building. Utilizing the historical energy data and local weather information, we evaluate the existing utility consumption and assign it to the various end-uses throughout the buildings. The Historical Data Analysis breaks down utilities by consumption, cost and annual profile.

This data is analyzed, using standard engineering assumptions and practices. The analysis serves the following functions:

- Allows our engineers to benchmark the energy and water consumption of the facilities against consumption of efficient buildings of similar construction, use and occupancy.
- Generates the historical and current unit costs for energy and water
- Provides an indication of how well changes in energy consumption correlate to changes in weather.
- Reveals potential opportunities for energy consumption and/or cost reduction. For example, the analysis may indicate that there is excessive, simultaneous heating and cooling, which may mean that there is an opportunity to improve the control of the heating and cooling systems.

By performing this analysis and leveraging our experience, our engineers prioritize buildings and pinpoint systems for additional investigation during the site visit, thereby maximizing the benefit of their time spent on site and minimizing time and effort by the customer's personnel.

Utility Rates used for Cost Analysis

Electricity (Blended Rate)	Natural Gas	Water/Sewer
\$0.13/kWh	.61/therm	\$ 4.81/ccf

The data analyzed provides the following information: 1) breakdown of utilities by consumption, 2) cost and annual profile, 3) baseline consumption in terms of energy/utility at the facility, 4) the Energy Use Index, or Btu/sq ft, and cost/sq ft. For multiple water meters, the utility data is combined to illustrate annual consumption for each utility type.



12.1. ELECTRICITY

PSEG satisfies the electricity requirements of the facility

Based on the 2013 electric usage and costs, the average price paid during the year was \$0.13 per kWh. The total annual electricity consumption for the 12-month period analyzed is 1,056,615 kWh for a total cost of \$139,659.16.

Electricity Consumption and Cost Data

Month	Consumption (kWh)	Unit Cost	Total Cost
January	143,758	\$0.12	\$17,728.86
February	141,348	\$0.13	\$18,476.34
March	152,386	\$0.14	\$21,816.42
April	58,173	\$0.15	\$8,851.86
May	44,098	\$0.14	\$6,141.46
June	52,549	\$0.14	\$7,619.17
July	62,911	\$0.16	\$9,888.20
August	71,969	\$0.16	\$11,320.65
September	61,070	\$0.15	\$9,371.16
October	58,775	\$0.12	\$6,926.53
November	83,887	\$0.09	\$7,867.70
December	125,691	\$0.11	\$13,650.81
Total	1,056,615	\$0.13	\$139,659.16





12.2. NATURAL GAS

PSEG satisfies the natural gas requirements of the facility.

Based on the 2013 natural gas usage and costs, the average price paid during the year was \$0.61 per therm. The total annual natural gas consumption for the 12-month period analyzed is 8,620 therms for a total cost of \$5,255.

Natural Gas Consumption and Cost Data

Month	Delivery (Therms)	Unit Cost	Total Cost
January	916	\$1.02	\$931.00
February	975	\$0.52	\$506.00
March	825	\$0.56	\$463.00
April	672	\$0.60	\$401.00
May	657	\$0.61	\$398.00
June	521	\$0.58	\$301.00
July	502	\$0.54	\$273.00
August	557	\$0.54	\$299.00
September	560	\$0.54	\$302.00
October	633	\$0.54	\$339.00
November	872	\$0.55	\$482.00
December	930	\$0.60	\$560.00
Total	8,620	\$0.61	\$5,255.00





12.3. WATER AND SEWER

City of Ridgewood satisfies the water and sewer requirements of the facility.

Based on the 2013 water and sewer usage and costs, the average price paid during the year was \$4.81 per ccf. The total annual water and sewer consumption for the 12-month period analyzed is 2,545 ccf for a total cost of \$12,229.

Water and Sewer Consumption and Cost Data

Month	Consumption (CCF)	Unit Cost	Total Cost
January	560	\$4.90	2,743
February	0	0	0
March	0	0	0
April	668	\$4.89	3,266
May	0	0	0
June	0	0	0
July	633	\$4.73	2,994
August	0	0	0
September	0	0	0
October	684	\$4.72	3,226
November	0	0	0
December	0	0	0
Total	2,545	\$4.81	\$12,229.00



13. HUD BENCHMARKING

The HUD Benchmarking tools provide a comparison of the energy and water consumption at multi-family properties against HUD's portfolio. The benchmarking tools take into account the property location, size, and configuration to rank the subject property amongst similar building. The result is a percentile score which indicates the percentage properties that the building performing better than. A score of 50 indicates average performance, while a score of 75 would indicate that the property is performing better than 75% of peer buildings.

The results from the utility analysis and the HUD Water Benchmarking Tool indicate that the subject property is slightly above the average benchmark for water consumption with a 46 out of 100 as scored against peers.

HUD Residential Water Use Benchmarking Tool
 For single-family, semi-detached, row/townhouse, multi-family walk-up and elevator buildings.

The HUD Residential Water Use Benchmarking Tool quantifies the performance of a user-defined building relative to the family of HUD residential buildings. A score of 75 denotes performance at the top 25th percentile of HUD residential buildings. A score of 50 denotes performance at the 50th percentile (in the middle) of HUD residential buildings. For definitions or help on the terms below, simply click on any underlined text. Click on "Return" text to come back to this page.

Directions: Provide entries in the gray spaces below with your **building description** and **annual water consumption**.

Building Description ORNL 8/22/2007

Building Name: (optional entry)
 5-digit Zip Code:
 Mapping Location: Paterson, NJ

Building(s) is
 Single-Family
 Detached or
 Semi-
 Area of
 Building(s) (ft2)

Is Residents
 Water Use
 Paid Directly
 by the PHA?
 (Y/N)

Number of Units
 in Building(s) with
 In-Unit Laundry
 Hookups or
 Units in
 Building(s) Central Laundry
 Access?

How Many
 Buildings
 share this
 Water
 Meter?

Building Description:

Annual Consumption

Building Annual Water Use: (gallons/year)

Building Annual Water Use Cost: (\$/year)

Average Annual Water Cost: \$0.6 (\$/100 gallons)

Results

	Your Building	HUD Typical
Score Against Peers	46	50
Annual Water Use (gal/year)	1,903,792	1,784,945
Annual Water Use Intensity (gal/ft2-year)	18.2	17.1
Annual Water Cost Intensity (\$/ft2-year)	0.12	0.11
Total Annual Water Cost (\$/year)	12,229	11,466

The results from the utility analysis and the HUD Energy Benchmarking Tool indicate that the subject property is slightly below average for energy consumption with a 67 out of 100 as scored against peers.

HUD Residential Energy Use Benchmarking Tool

For single-family, semi-detached, row/townhouse, multi-family walk-up, and elevator buildings.

The HUD Residential Energy Use Benchmarking Tool quantifies the performance of a user-defined building relative to the family of HUD residential buildings. A score of 75 denotes performance at the top 25th percentile of HUD residential buildings. A score of 50 denotes performance at the 50th percentile (in the middle) of HUD residential buildings. For definitions or help on the terms below, simply click on any underlined text. Click on "Return" to come back to this page.

Directions: Provide entries in ALL the grey spaces that apply for your **Building Description** and **Annual Energy Consumption**.

Building Description

Preliminary: 9/17/07

Building Name: (optional entry)

5-digit Zip Code: Heating Degree Days:

Mapping Location: Paterson, NJ Cooling Degree Days:

Is This a Multifamily Building? ☐ Is this a Multi-Family Building with Central Laundry? ☐ Family Walkup Building? ☐ Heated Floor Area (ft²) Year Built

Annual Consumption

Select Units: Electricity Gas #2 Fuel Oil #4 Fuel Oil District Steam District Hot Water Propane

	Electricity	Gas	#2 Fuel Oil	#4 Fuel Oil	District Steam	District Hot Water	Propane
Energy	1,056,615	8,620					
Cost (\$)	139,659	5,255					
Calculated unit cost:	\$0.13 \$/kWh	\$0.61 \$/therm					

Results

	Your Building	HUD Typical
Score Against Peers	67	50
Building Site Energy Use (kBtu/year)	4,467,170	5,462,973
Site Energy Use Intensity (kBtu/ft ² -year)	42.7	52.2
Energy Cost Intensity (\$/ft ² -year)	1.39	1.69
Total Annual Energy Cost (\$/year)	144,914	177,218

The graph shows a diagonal line from 'High' energy intensity at a performance rating of 1 to 'Low' energy intensity at a performance rating of 100. A dashed horizontal line from the 'Your Building' score of 67 on the x-axis meets the diagonal line, and a dashed vertical line drops from that point to the x-axis at 67.

14. RECOMMENDED OPERATIONS AND MAINTENANCE PLAN

The quality of the maintenance and the operation of the facility's energy systems have a direct effect on its overall energy efficiency. Energy-efficiency needs to be a consideration when implementing facility modifications, equipment replacements, and general corrective actions. The following is a list of activities that should be performed as part of the routine maintenance program for the property. These actions, which have been divided into specific and general recommendations, will insure that the energy conservation measures identified in this report will remain effective. The following general recommendations should be continued or implemented.

Building Envelope

1. Caulking and weather stripping functional and effective at all times
2. Walls observed periodically and holes patched in the building envelope as required
3. Windows inspected periodically for damaged panes and failed thermal seals
4. Automatic door closing mechanisms repaired and adjusted as needed

Heating and Cooling

1. Air filters inspected periodically and replaced prior to excessive visual buildup (May increase filter costs, but will reduce fan energy costs)
2. Boiler tubes inspected and cleaned annually
3. Temperature settings reduced in unoccupied areas and set points seasonally adjusted.
4. Control valves and dampers checked for functionality monthly and repaired, when needed
5. Equipment inspected for worn or damaged parts as part of a monthly maintenance check
6. Ductwork visually inspected and checked for leaks or damaged insulation as part of a monthly maintenance check
7. Hot air registers and return air ductwork clean and unobstructed
8. Air dampers operating correctly

Domestic Hot Water

1. Domestic water heater temperature set to the minimum temperature required
2. Hot water piping checked routinely for damaged insulated and leaks
3. Tank-type water heaters flushed monthly

Lighting

1. Over-lit areas managed by bi-level switching or photocell controls
2. Only energy-efficient replacement lamps used and in-stock for replacement
3. Lighting fixture reflective surfaces and translucent covers clean
4. Walls clean and bright to maximize lighting effectiveness
5. Timers and/or photocells operating correctly on exterior lighting

Existing Equipment and Replacements

1. Refrigerator and freezer doors closed and sealed correctly
2. Kitchen exhaust fans only used when needed or timers installed to limit operation
3. Office/ computer equipment either in the "sleep" or "off" mode when not used
4. All other recommended equipment specific preventive maintenance actions conducted

15. APPENDICES

- APPENDIX A: Photographic Record
- APPENDIX B: Site Plan
- APPENDIX C: Supporting Documentation
- APPENDIX D: EMG Accessibility Checklist
- APPENDIX E: Pre-Survey Questionnaire
- APPENDIX F: Acronyms
- APPENDIX G: Glossary of Terms-Energy Audits
- APPENDIX H: Energy Conservation Measures

APPENDIX A:
PHOTOGRAPHIC RECORD

EMG PHOTOGRAPHIC RECORD

Project No.: 107534.13R-009.308

Project Name: Ridgecrest Apartments



Photo #1: Exterior building elevation, partial roof overview



Photo #2: Parking provided adjacent to building



Photo #3: Front view, east elevation



Photo #4: Right side, north elevation



Photo #5: Rear view, west elevation



Photo #6: Left side, south elevation

EMG PHOTOGRAPHIC RECORD

Project No.: 107534.13R-009.308

Project Name: Ridgecrest Apartments



Photo #7: Parking stalls and drive aisle



Photo #8: Concrete sidewalk throughout property



Photo #9: Drainage



Photo #10: Retention wall on west side of property



Photo #11: Concrete walls throughout property



Photo #12: Garden beds throughout property

EMG PHOTOGRAPHIC RECORD

Project No.: 107534.13R-009.308

Project Name: Ridgecrest Apartments



Photo #13: Majority of roof is 20 year 3-tab shingles



Photo #14: Small sections of roof have rubber roofing




Photo #15: Exterior wall brick veneer



Photo #16: Exterior stairs at grade changes



Photo #17: Interior stairwell



Photo #18: Sliding windows throughout building

EMG PHOTOGRAPHIC RECORD

Project No.: 107534.13R-009.308

Project Name: Ridgecrest Apartments



Photo #19: Metal exit doors with lever handles



Photo #20: Tenant entry door



Photo #21: One of two laundry rooms



Photo #22: Library/recreation room



Photo #23: Common area bathroom



Photo #24: Main lobby

EMG PHOTOGRAPHIC RECORD

Project No.: 107534.13R-009.308

Project Name: Ridgecrest Apartments



Photo #25: Community room



Photo #26: Building hallway



Photo #27: Condenser for community room



Photo #28: Air handler for community room



Photo #29: PTAC units throughout common areas



Photo #30: Domestic hot water boiler

EMG PHOTOGRAPHIC RECORD

Project No.: 107534.13R-009.308

Project Name: Ridgecrest Apartments



Photo #31: Emergency generator



Photo #32: Elevator (one of two)



Photo #33: Strobes throughout building



Photo #34: Sprinklers throughout common areas



Photo #35: Unit kitchen



Photo #36: Tenant bathroom

EMG PHOTOGRAPHIC RECORD

Project No.: 107534.13R-009.308

Project Name: Ridgecrest Apartments



Photo #37: Unit living room



Photo #38: Unit bedroom



Photo #39: Electric range and refrigerator in every unit kitchen




Photo #40: PTAC unit in every tenant apartment



Photo #41: Electric panel in each unit

APPENDIX B:
SITE PLAN

Site Plan



Key:

Red-Property border
Black-Property buildings
Purple-Surrounding buildings

Blue-Parking and drive lanes
Orange-Main roads



Not drawn to scale.
The north arrow indicator is an approximation of 0° North.

Project Number:

107534.13R-009.308

Project Name:

Ridgecrest Apartments

On-Site Date:

April 9, 2014

APPENDIX C:
SUPPORTING DOCUMENTATION

BUILDING DEPARTMENT FOIA

To: David Moody
Ridgewood Building Department
Ridgewood, New Jersey

Date: April 9, 2014
Phone #: 609.633.6225
Fax #
:

Re: Ridgecrest Apartments
7-11 Ridge Road
Ridgewood, New Jersey 07450

EMG Project No: 107534.13R-009.308

Project Manager: David Jacques

Dear David Moody:

EMG is an engineering firm currently conducting a property condition survey of the above-referenced property. As part of the due-diligence process, we are submitting this letter through the Freedom of Information Act to obtain information specific to the property. We request your assistance by providing us with the following information concerning the site and buildings:

1. Date of last building department inspection ___/___/___
mo. day year
2. Are there any OUTSTANDING building code violations? YES / NO
(circle one)
3. How often is the subject property inspected? annually, biennially, other
(circle one)
4. Is the original Certificate of Occupancy or Permit on file? YES / NO
If such documents are on file, please fax them to the number noted below.

Responses may be faxed directly to our office, at (410) 785-6220, or mailed to our corporate offices:

EMG
Attn: Senior Engineering Consultant
222 Schilling Circle, Suite 275
Hunt Valley, Maryland 21031

If **outstanding** violations are on file, please provide copies of the reports/citations. Please note the EMG Project Number and the Senior Engineering Consultant's name on all correspondence. If you need additional information to complete this request, please contact me at (800) 733-0660. Thank you for your prompt attention to this matter.

Sincerely,

David Jacques
Project Manager

FIRE DEPARTMENT FOIA

To: Ridgewood Fire Department
Address
Ridgewood, New Jersey

Date: April 9, 2014
Phone #:
Fax #:

Re: Ridgecrest Apartments
7-11 Ridge Road
Ridgewood, New Jersey 07450

EMG Project No: 107534.13R-009.308

Project Manager: David Jacques

Dear Sir/Madam:

EMG is an engineering firm currently conducting a property condition survey of the above-referenced property. As part of the due-diligence process, we are submitting this letter through the Freedom of Information Act to obtain information specific to the property. We request your assistance by providing us with the following information concerning the site and buildings:

1. Date of last fire department inspection ____/____/____
mo. day year
2. Are there any OUTSTANDING fire code violations? YES / NO
(circle one)
3. How often is the subject property inspected? annually, biennially, other
(circle one)

Responses may be faxed directly to our office, at (410) 785-6220, or mailed to our corporate offices:

EMG
Attn: Senior Engineering Consultant
222 Schilling Circle, Suite 275
Hunt Valley, Maryland 21031

If **outstanding** violations are on file, please provide copies of the reports/citations. Please note the EMG Project Number and the Senior Engineering Consultant's name on all correspondence. If you need additional information to complete this request, please contact me at (800) 733-0660. Thank you for your prompt attention to this matter.

Sincerely,
David Jacques
Project Manager

APPENDIX D:
EMG ACCESSIBILITY CHECKLIST

EMG ACCESSIBILITY CHECKLIST

Property Name: Ridgecrest Apartments

Date: 4/9/14

Project Number: 107534.13R-009.308

EMG Accessibility Checklist						
UFAS/ADA Accessibility						
	Building History	Yes	No	N/A	Unk	Comments
1.	Has the management previously completed an accessibility review?	√				
2.	Does an accessibility compliance plan exist for the property?	√				
3.	Has the plan been reviewed/approved by outside agencies (engineering firms, building department, other agencies)?			√		
4.	Have any accessibility related complaints been received in the past?		√			
5.						
	Building Access	Yes	No	N/A	Comments	
1.	Are there an adequate number (per regulation) of wheelchair accessible parking spaces available at the rental office (96" wide/ 60" aisle)	√				
2.	Is there at least one wheelchair accessible van parking space (96" wide/ 96" aisle) for every 8 standard accessible spaces?	√				
3.	Are accessible parking spaces located on the shortest accessible route of travel from an accessible building entrance?	√				
4.	Does signage exist directing you to wheelchair accessible parking and an accessible building entrance?	√				
5.	Is there a ramp from the parking to an accessible building entrance (1:12 slope or less)	√				
6.	If the main entrance is inaccessible, are there alternate accessible entrances?	√				
7.	Is the accessible entrance doorway at least 32" wide?	√				

EMG Accessibility Checklist					
	Building Access	Yes	No	N/A	Comments
8.	Is the door handle easy to open? (lever/push type knob, no twisting required, no higher than 48" above floor)	√			
9.	Are entry doors other than revolving doors available?	√			
	Rental office	Yes	No	N/A	Comments
1.	Is the entry door to the rental office 3'wide with no step or threshold over ½" tall?	√			
2.	Is there a counter or table at 30" high for wheelchair access to fill out a rental application?	√			
3.	Is there clearance behind the counter for an employee in a wheelchair?	√			
	Building Corridors and Elevators	Yes	No	N/A	Comments
1.	Is the path of travel free of obstructions and wide enough for a wheelchair (at least 60" wide)?	√			
2.	Are floor surfaces firm, stable and slip resistant (carpets wheelchair friendly)?	√			
3.	Do obstacles (phones, fountains, etc.) protrude no more than 4" into walkways or corridor?		√		
4.	Are elevators controls low enough to be reached from a wheelchair (48" front approach/54" side approach)?	√			
5.	Are there raised elevator markings in Braille and standard alphabet for the blind?	√			
6.	Are there audible signals inside cars indicating floor changes?	√			
7.	Do elevator lobbies have visual and audible indicators of the cars arrival?	√			
8.	Does the elevator interior provide sufficient wheelchair turning area (51" x 68" minimum)?	√			
9.	Is at least one wheelchair accessible public phone available?	√			
10	Are wheelchair accessible facilities (restrooms, exits, etc.) identified with signage?	√			

EMG Accessibility Checklist					
	Common Area Restrooms	Yes	No	N/A	Comments
1.	Are common area public restrooms located on an accessible route?	√			
2.	Are pull handles push/pull or lever type?	√			
3.	Are access doors wheelchair accessible (at least 32" wide)?	√			
4.	Are public restrooms large enough for wheelchair turnaround (60" turning diameter)?	√			
5.	Are stall doors wheelchair accessible (at least 32" wide)?	√			
6.	If stalls are too narrow can the toilet room be converted to a single occupant toilet room?			√	Not necessary
7.	Are grab bars provided in toilet stalls (33"-36" above floor)?	√			
8.	Do sinks provide clearance for a wheelchair to roll under (29" clearance)?	√			
9.	Are sink handles operable with one hand without grasping, pinching or twisting?	√			
10.	Are exposed pipes under sink sufficiently insulated against contact?	√			
11.	Are soap dispensers, towel, etc. reachable (48" from floor for frontal approach, 54" for side approach)?	√			
12.	Is the base of the mirror no more than 40" off floor?	√			
	Common Area Kitchen	Yes	No	N/A	Comments
1.	In a "U"-shaped kitchen is there 60" clear floor space width?			√	
2.	In a "U"-shaped kitchen with base cabinet removed from beneath sink, is there a minimum of 40" width?			√	
3.	In a "L"-shaped kitchen, is there a 40" width minimum maintained?	√			
4.	Are countertops a maximum of 24" deep and 36" high?	√			
5.	Knee space beneath cabinetry is 30" wide and 27" high.	√			
6.	Is insulation installed below sinks on piping?	√			
7.	Are adaptable units equipped with removable or retractable cabinetry fronts beneath sink or stove?	√			

EMG Accessibility Checklist					
	Common Area Laundry rooms	Yes	No	N/A	Comments
1.	Are the laundry rooms located on an accessible route?	√			
2.	Are the door handles push/pull or lever type?	√			
3.	Are the access doors wheelchair accessible (at least 32" clear width)?	√			
4.	Are laundry rooms large enough for wheelchair turnaround (60" turning diameter)?	√			
5.	Is there a front load washing machine	√			
6.	If clothes folding tables are provided is one section at 32" high with a clear area below the table?	√			
Fair Housing Accessibility / Section 504					
	Access to Unit	Yes	No	N/A	Comments
1.	Property management reports that the number of units currently accessible and those adaptable meet FHA requirements of all ground floor units or 100% for a high rise.	√			
2.	Are 5% of the units fully accessible to those individuals with mobility impairments and 2% of units accessible to those individuals with audio / visual impairments?	√			
3.	Are there any barriers or structural restrictions preventing access to the building?		√		
4.	Are the accessible units on an accessible route?	√			
5.	Is the apartment entry corridor 36" wide, door 32" wide (frame to frame), threshold height less than ½", and appropriate door hardware present?	√			
	Unit Living Space	Yes	No	N/A	Comments
1.	Is there access throughout unit?	√			
2.	Are electrical outlets 15" minimum above floor minimum?	√			
3.	Are environmental controls and switches 48" maximum above floor or lower?	√			
	Unit Bathroom	Yes	No	N/A	Comments
1.	Is entry door at least 32" wide frame-to-frame?	√			

EMG Accessibility Checklist					
	Unit Bathroom	Yes	No	N/A	Comments
2.	Are switches & outlets in accessible locations?	√			
3.	Are bathroom walls around the toilet and tub/shower reinforced?	√			
4.	Is there a 30" x 48" clear floor space outside of door swing area?	√			
5.	Is there a 56" x 48" clear floor space in front of toilet (48" out from wall toilet is hung against)?	√			
6.	Is there a 30" x 48" clear floor space in front of lavatories (30" deep from front of counter)?	√			
7.	Is there a 30" x 48" clear floor space in front of tub/shower (30" out from tub/shower)?	√			
8.	Is vanity a maximum of 24" deep and 36" high?	√			
9.	Knee space beneath sink is 30" wide and 27" high.	√			
10.	Is shower stall 36"x 42" minimum with small lip?	√			
11.	Is insulation installed below sinks on piping?	√			
	Unit Kitchen	Yes	No	N/A	Comments
1.	In a "U"-shaped kitchen is there 60" clear floor space width?			√	
2.	In a "U"-shaped kitchen with base cabinet removed from beneath sink, is there a minimum of 40" width?			√	
3.	In a "L"-shaped kitchen, is there a 40" width minimum maintained?	√			
4.	Are countertops a maximum of 24" deep and 36" high?	√			
5.	Knee space beneath cabinetry is 30" wide and 27" high.	√			
6.	Is insulation installed below sinks on piping?	√			
7.	Are adaptable units equipped with removable or retractable cabinetry fronts beneath sink or stove?	√			

It is understood by the Client that the limited observation described herein does not comprise a full ADA Compliance Survey, and that such a survey is beyond the scope of EMG's Physical Condition Assessment. Only a representative sample of areas was observed and, other than as shown on the accessibility checklist, actual measurements were not taken to verify compliance.

APPENDIX E:
PRE-SURVEY QUESTIONNAIRE

PROPERTY CONDITION ASSESSMENT: PRE-SURVEY QUESTIONNAIRE

This questionnaire must be completed by the property owner, the owner's designated representative, or someone knowledgeable about the subject property. **The completed form must be presented to EMG's Field Observer on the day of the site visit.** If the form is not completed, EMG's Project Manager will require **additional time** during the on-site visit with such a knowledgeable person in order to complete the questionnaire. During the site visit, EMG's Field Observer may ask for details associated with selected questions. This questionnaire will be utilized as an exhibit in EMG's final Property Condition Report.

Name of person completing
questionnaire:

Riya Gordin.

Association with property:

MBL.

Length of association with property:

11 yrs.

Date Completed:

1-29-14

Phone Number:

201 9544558

Property Name:

MOORE CREST APTS.

EMG Project Number:

Directions: Please answer all questions to the best of your knowledge and in good faith. Please provide additional details in the Comments column, or add backup documentation for any Yes responses.

INSPECTIONS		DATE LAST INSPECTED	LIST ANY OUTSTANDING REPAIRS REQUIRED
1	Elevators	2-14-14 10-13 KIN	
2	HVAC, Mechanical, Electric, Plumbing		ONGOING BASIS
3	Life-Safety/Fire	1-21-14 COOR. 8-5-13 TOWN	ANNUAL. + 3 1/4 YRS. } EAT MONTHLY
4	Roofs		ONGOING BASIS.
QUESTION		RESPONSE	
5	List any major capital improvement within the last three years.	NEW GENERATOR + SWITCHGEAR NEW F/A PANEL.	
6	List any major capital expenditures planned for the next year.	APT ELEC PANEL REPL (13) DOMESTIC HW/BOILER + HOLDING TANK	
7	What is the age of the roof(s)?	Approx 6-7 yrs.	
8	What building systems (HVAC, roof, interior/exterior finishes, paving, etc.) are the responsibilities of the tenant to maintain and replace?	NONE.	

Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any Yes responses. (NA indicates "Not Applicable", Unk indicates "Unknown")


QUESTION		RESPONSE				COMMENTS
		Y	N	Unk	NA	
9	Are there any unresolved building, fire, or zoning code issues?		X			
10	Are there any "down" or unusable units?		X			
11	Are there any problems with erosion, stormwater drainage or areas of paving that do not drain?		X			
12	Is the property served by a private water well?		X			
13	Is the property served by a private septic system or other waste treatment systems?	X				SEWAGE HOLDING TANK PUMP STATION
14	Are there any problems with foundations or structures?		X			
15	Is there any water infiltration in basements or crawl spaces?		X			
16	Are there any wall, or window leaks?		X			
17	Are there any roof leaks?		X			
18	Is the roofing covered by a warranty or bond?	X				
19	Are there any poorly insulated areas?		X			
20	Is Fire Retardant Treated (FRT) plywood used?			X		
21	Is exterior insulation and finish system (EIFS) or a synthetic stucco finish used?		X			
22	Are there any problems with the utilities, such as inadequate capacities?		X			
23	Are there any problems with the landscape irrigation systems?		X			
24	Has a termite/wood boring insect inspection been performed within the last year?		X			
25	Do any of the HVAC systems use R-11, 12, or 22 refrigerants?		X			

Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any Yes responses. (NA indicates "Not Applicable", Unk indicates "Unknown")

QUESTION		RESPONSE				COMMENTS
		Y	N	UNK	NA	
26	Has any part of the property ever contained visible suspect mold growth?		X			
27	Is there a mold Operations and Maintenance Plan?		X			
28	Have there been indoor air quality or mold related complaints from tenants?		X			
29	Is polybutylene piping used?		X			
30	Are there any plumbing leaks or water pressure problems?		X			
31	Are there any leaks or pressure problems with natural gas service?		X			
32	Does any part of the electrical system use aluminum wiring?		X			
33	Do Residential units have a less than 60-Amp service?		X			
34	Do Commercial units have less than 200-Amp service?		X		X	
35	Are there any recalled fire sprinkler heads (Star, GEM, Central, Omega)?		X			
36	Is there any pending litigation concerning the property?		X			
37	Has the management previously completed an ADA review?	X				504 COMPLIANCE 2009.
38	Have any ADA improvements been made to the property?	X				2 H/C RACES - APTS Roll-in SHOWERS installed
39	Does a Barrier Removal Plan exist for the property?		X			
40	Has the Barrier Removal Plan been approved by an arms-length third party?				X	
41	Has building ownership or management received any ADA related complaints?		X			
42	Does elevator equipment require upgrades to meet ADA standards?	X				ELEV. CAB + MOTOR REPL. CAP EX FOR. 2015

Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any Yes responses. (NA indicates "Not Applicable", Unk indicates "Unknown")

QUESTION		RESPONSE				COMMENTS
		Y	N	UNK	NA	
43	Are there any problems with exterior lighting?	X				NOT LED Energy EFFICIENT
44	Are there any other significant issues/hazards with the property?		X			
45	Are there any unresolved construction defects at the property?		X			



 Signature of person Interviewed or completing form

1-29-14

 Date

PROPERTY CONDITION ASSESSMENT: DOCUMENT REQUEST

On the day of the site visit, provide EMG's Field Observer access to all of the available documents listed below. Provide copies if possible. Your timely compliance with this request is greatly appreciated.

- 1/10* • A site plan, preferably 8 1/2" X 11", which depicts the arrangement of buildings, roads, parking stalls, and other site features.
- 1/10* • Diagram floor plan of each floor level at 8 1/2" X 11" with room numbers.
- ✓* • Any available construction documents (blueprints) for the original construction of the building or for any tenant improvement work or other recent construction work.
- 1/10* • ~~For commercial properties, provide a tenant list which identifies the names of each tenant, vacant tenant units, the floor area of each tenant space, and the gross and net leasable area of the building(s).~~
- For apartment properties, provide a summary of the apartment unit types and apartment unit type quantities, including the floor area of each apartment unit as measured in square feet.
- ~~For hotel or nursing home properties, provide a summary of the room types and room type quantities.~~
- OK* • Copies of Certificates of Occupancy, building permits, fire or health department inspection reports, elevator inspection certificates, roof or HVAC warranties, or any other similar, relevant documents.
- OK* • The names of the local utility companies which serve the property, including the water, sewer, electric, gas, and phone companies. ~~SEEG~~ *PSEG. 11046 wood water*
- Check list* • The company name, phone number, and contact person of all outside vendors who serve the property, such as mechanical contractors, roof contractors, fire sprinkler or fire extinguisher testing contractors, and elevator contractors.
- A summary of recent (over the last 5 years) capital improvement work which describes the scope of the work and the estimated cost of the improvements. Executed contracts or proposals for improvements. Historical costs for repairs, improvements, and replacements.
- Records of system & material ages (roof, MEP, paving, finishes, and furnishings).
- Any brochures or marketing information. *NONE*
- ?* • Appraisal, either current or previously prepared. *?*
- 99% 12 mo. yr* • Current occupancy percentage and typical turnover rate records (for commercial and apartment properties).
- LAW.* • Previous reports pertaining to the physical condition of property.
- LAW.* • ADA survey and status of improvements implemented.
- none.* • Current / pending litigation related to property condition.

ENERGY AUDIT : PRE-SURVEY QUESTIONNAIRE

This questionnaire must be completed by the property owner, management point of contact or other person knowledgeable about the subject property.

The completed form must be presented to EMG's Field Observer on or before the site visit.

If the form is not completed, EMG's Project Manager will require additional time during the on-site visit in order to complete the questionnaire. During the site visit, EMG's Field Observer may ask for details associated with selected questions. This questionnaire will be utilized as an exhibit in EMG's final report.

Housing Authority: <i>OF Bergen CTY</i>	Address: <i>HAUTENSACK AVE 07601</i>	
Owner, if other than Authority: <i>RIDGEWOOD SENIOR CITIZENS HONORARY</i>	Address: <i>9- RIDGE RD.</i> <i>RIDGEWOOD NJ 07450</i>	
Name of Subject Site: <i>RIDGE CREST APTS.</i>	Residential Buildings: <i>2</i>	Common Buildings: Other Buildings: <i>1 SHED.</i>
Address: <i>9-11 RIDGE RD.</i>	City, State, Zip <i>RIDGEWOOD NJ 07450</i>	
Building Manager <i>RIEN COODIN</i>	Phone <i>201 954 4558</i>	
Maintenance Manager <i>NONE</i>	Phone	
Energy Management Coordinator <i>NONE</i>	Phone	
Building Description (circle all that apply) Masonry <input checked="" type="checkbox"/> Wood framed <input checked="" type="checkbox"/> Steel framed <input type="checkbox"/> Curtain wall Detached <input type="checkbox"/> Townhouse <input type="checkbox"/> Low-rise <input checked="" type="checkbox"/> Mid-rise <input type="checkbox"/> High-rise Basement <input type="checkbox"/> Crawl Space <input type="checkbox"/> Attic <input checked="" type="checkbox"/> Flat Roof <input checked="" type="checkbox"/> Slope Roof		Other uses on this site <input checked="" type="checkbox"/> Rental Office <input type="checkbox"/> Community Service Offices <input checked="" type="checkbox"/> Common Laundry <input checked="" type="checkbox"/> Common Meeting-Activity <input checked="" type="checkbox"/> Common Kitchen <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Commercial <input type="checkbox"/> Daycare <input type="checkbox"/> Training Education <input type="checkbox"/> Gym Fitness Recreation <input checked="" type="checkbox"/> Maintenance Storage <input type="checkbox"/> Other, Specify:
Number of: ___ Efficiencies ___ One BR ___ Two BR ___ Three BR ___ Four BR ___ Five BR ___ Six BR ___ SRO Date of original completion _____ Dates of significant renovations _____ Describe:		
Anticipated Modifications or Changes in Use in the next 15 yrs: <i>REPLACE ELEVATOR PANEL REPL. / ELEVATOR MOD (15)</i> <i>DOOR IN HW. BLK + WORK REPL. / RESURFACE PARKING LOT (16)</i>		
Have there been previous Energy Audits or Retrofit Programs? <input checked="" type="checkbox"/> Yes ___ No Date <i>2011</i> Agency <i>IN HONOR.</i> Scope <i>REPLACED ALL COMMON AREA LIGHTS TIL'S TO V'S - EXISTING WOLLED - INCREASED TO CORP ACT FLOORING</i> Are related Energy Audit or Retrofit documents available? <i>NONE</i> Any additional Energy Investment Programs? <i>N/A</i>		

Does the Institution Have an ongoing energy management program? ___Yes ___No

Utilities			
	Utility Supplier to the Site	Master Metered	Tenant Metered
Electric	PSEG	✓	✓
Natural/LP Gas	_____		
Fuel Oil	RACHALLES MICHELLES (GEN)	✓	
Other _____			
Domestic Water	UNITED WATER.	✓	
Sewer	N/A.		

- Utility data is required for the most recent available 12 month period. EMG can provide you with Excel form to assist you in supplying this data. Request this form from your Program Manager.
- Tenant paid data is required for best evaluation results. At minimum a representative sample of actual tenant consumption and cost is required for the 12 month period.

Tenant Utility Cost Paid By		
	Landlord or Housing Authority	Tenant
Heating		X
Cooling		X
Domestic Hot Water	X	
Water Supply	X	
Sewer	X	

Unk = Unknown, NA = Not Applicable	Yes	No	Unk	NA	Comments
1. Does the boiler or furnaces seem to be oversized for the property (i.e. – cycles on and off often)?		X			
2. Do any of the gas fired boilers, furnaces, or water heaters have vent or flue dampers?	X				
3. Does the boiler have outdoor reset controls?		X			
4. Does the County pay for the tenant gas or oil consumption?		X			
5. Are low-flow faucet aerators and shower heads installed on all or most faucets and showers?	X				
6. Are the water closets low-flow (1.6 gpf)?		X			
7. Are the motors used for the elevators					

Unk = Unknown, NA = Not Applicable	Yes	No	Unk	NA	Comments
high-efficiency motors?		X			
8. Are the motors used for the ventilation systems (i.e. - air handlers, fan coils, etc.) high-efficiency motors?		X			
9. Are the motors used for the hydronic heating system (i.e. - pumps) high-efficiency motors?		X		X	
10. Are the motors used for the hydronic cooling system (i.e. - pumps, chillers, cooling tower fan) high-efficiency motors?				X	
11. Is there any uninsulated heating water, chilled water, or domestic hot water piping in unconditioned spaces such as mechanical rooms, basements, or storage areas?		X			
12. Is a booster pump required to maintain water pressure at the property?		X			
13. Are laundry room washing machines fixed to cold rinse only?		X			
14. Are there any wall or window leaks?		X			
15. Are there any poorly insulated areas?		X			
16. Do the utilities (electric, gas, sewer, water) provide adequate service?	X				
17. Are HVAC systems at the property inspected and maintained, at a minimum, annually?	X				
18. Is the HVAC equipment more than ten years old?	X				upgrades HAVE BEEN MADE
19. Are the water heaters/boilers more than ten years old?	X				TO BE REPL. (14)
20. Are there any leaks or pressure problems with natural gas service?		X			
21. Is the electrical service adequate?	X				
22. Are there any emergency electrical generators?	X				
23. Are there any large UPS battery systems?		X			
24. Are there any vacant buildings or significant building areas?		X			
25. Is there anything else that EMG should know about when assessing this property? If so, what?		X			

On the day of the site visit, provide EMG's Field Observer access to all of the available documents listed below. Provide copies if possible.

<p>INFORMATION REQUIRED</p> <ol style="list-style-type: none">1. All available construction documents (blueprints) for the original construction of the building or for any tenant improvement work or other recent construction work.2. A site plan, preferably 8 1/2" X 11", which depicts the arrangement of buildings, roads, parking stalls, and other site features.3. For commercial properties, provide a tenant list which identifies the names of each tenant, vacant tenant units, the floor area of each tenant space, and the gross and net leasable area of the building(s).4. For apartment properties, provide a summary of the apartment unit types and apartment unit type quantities, including the floor area of each apartment unit as measured in square feet.5. For hotel or nursing home properties, provide a summary of the room types and room type quantities.6. Copies of Certificates of Occupancy, building permits, fire or health department inspection reports, elevator inspection certificates, roof or HVAC warranties, or any other similar, relevant documents.7. The names of the local utility companies which serve the property, including the water, sewer, electric, gas, and phone companies.	<ol style="list-style-type: none">8. The company name, phone number, and contact person of all outside vendors who serve the property, such as mechanical contractors, roof contractors, fire sprinkler or fire extinguisher testing contractors, and elevator contractors.9. A summary of recent (over the last 5 years) capital improvement work which describes the scope of the work and the estimated cost of the improvements. Executed contracts or proposals for improvements. Historical costs for repairs, improvements, and replacements.10. Records of system & material ages (roof, MEP, paving, finishes, furnishings).11. Any brochures or marketing information.12. Appraisal, either current or previously prepared.13. Current occupancy percentage and typical turnover rate records (for commercial and apartment properties).14. Previous reports pertaining to the physical condition of property.15. ADA survey and status of improvements implemented.16. Current / pending litigation related to property condition.
--	---

Your timely compliance with this request is greatly appreciated.

APPENDIX F: ACRONYMS

ASTM E2018-01 ACRONYMS

ADA - The Americans with Disabilities Act
ASTM - American Society for Testing and Materials
BOMA - Building Owners & Managers Association
BUR - Built-up Roofing
DWV – Drainage, Waste, Ventilation
EIFS - Exterior Insulation and Finish System
EMF – Electro Magnetic Fields
EMS - Energy Management System
EUL - Expected Useful Life
FEMA - Federal Emergency Management Agency
FFHA - Federal Fair Housing Act
FIRMS - Flood Insurance Rate Maps
FRT- Fire Retardant Treated
FOIA - U.S. Freedom of Information Act (5 USC 552 et seq.) and similar state statutes.
FOIL - Freedom of Information Letter
FM - Factory Mutual
HVAC - Heating, Ventilating and Air-conditioning
IAQ - Indoor Air Quality
MEP – Mechanical, Electrical & Plumbing
NFPA - National Fire Protection Association
PNA – Capital Needs Assessment
PCR - Property Condition Report
PML - Probable Maximum Loss
RTU - Rooftop Unit
RUL - Remaining Useful Life
STC – Sound Transmission Class
UBC – Uniform Building Code

APPENDIX G: GLOSSARY OF TERMS-ENERGY AUDITS

Glossary of Terms and Acronyms-Energy Audit

ECM – Energy Conservation Measures are projects recommended to reduce energy consumption. These can be No/Low cost items implemented as part of routine maintenance or Capital Cost items to be implemented as a capital improvement project.

Initial Investment – The estimated cost of implementing an ECM project. Estimates typically are based on R.S. Means Construction cost data and Industry Standards.

Annual Energy Savings – The reduction in energy consumption attributable to the implementation of a particular ECM. These savings values do not include the interactive effects of other ECMs.

Cost Savings – The expected reduction in utility or energy costs achieved through the corresponding reduction in energy consumption by implementation of an ECM.

Simple Payback Period –The number of years required for the cumulative value of energy or water cost savings less future non-fuel or non-water costs to equal the investment costs of the building energy or water system, without consideration of discount rates.

EUL – Expected Useful Life is the estimated lifespan of a typical piece of equipment based on industry accepted standards.

RUL – Remaining Useful Life is the EUL minus the effective age of the equipment and reflects the estimated number of operating years remaining for the item.

SIR - The savings-to-investment ratio is the ratio of the present value savings to the present value costs of an energy or water conservation measure. The numerator of the ratio is the present value of net savings in energy or water and non-fuel or non-water operation and maintenance costs attributable to the proposed energy or water conservation measure. The denominator of the ratio is the present value of the net increase in investment and replacement costs less salvage value attributable to the proposed energy or water conservation measure. It is recommended that energy-efficiency recommendations be based on a calculated SIR, with larger SIRs receiving a higher priority. A project typically is recommended only if the SIR is greater than or equal to 1.0, unless other factors outweigh the financial benefit.

Life Cycle Cost - The sum of the present values of (a) Investment costs, less salvage values at the end of the study period; (b) Non-fuel operation and maintenance costs; (c) Replacement costs less salvage costs of replaced building systems; and (d) Energy and/or water costs.

Life Cycle Savings – The sum of the estimated annual cost savings over the EUL of the recommended ECM, expressed in present value dollars.

Building Site Energy Use Intensity - The sum of the total site energy use in thousands of Btu per unit of gross building area. Site energy accounts for all energy consumed at the building location only not the energy consumed during generation and transmission of the energy to the site.

Building Source Energy Use Intensity – The sum of the total source energy use in thousands of Btu per unit of gross building area. Source energy is the energy consumed during generation and transmission in supplying the energy to your site.

Building Cost Intensity - This metric is the sum of all energy use costs in dollars per unit of gross building area.

Greenhouse Gas Emissions - Although there are numerous gases that are classified as contributors to the total for Greenhouse Emissions, the scope of this energy audit focuses on carbon dioxide (CO₂). Carbon dioxide enters the atmosphere through the burning of fossil fuels (oil, natural gas, and coal), solid waste, trees and wood products, and also as a result of other chemical reactions (e.g., manufacture of cement).

APPENDIX H: ENERGY CONSERVATION MEASURES

Replace Older Refrigerators with Energy Star Rated Refrigerators

Step 1a	Obtain total cost of replacing the older refrigerators with Energy Star rated refrigerators:	
	<input type="text" value="78"/> Units x <input type="text" value="\$579"/> each =	<input type="text" value="\$45,162"/> (Green Cost)
Step 1b	Obtain total cost of replacing the older refrigerators with traditional refrigerators:	
	<input type="text" value="78"/> Units x <input type="text" value="\$629"/> each =	<input type="text" value="\$49,062"/> (Traditional Cost)
Step 2	Refrigerator and Utility Information:	
a	Total number of refrigerators to be replaced	<input type="text" value="78"/>
b	Useful Life refrigerators:	<input type="text" value="15"/> years
c	Average age of existing refrigerators:	<input type="text" value="20"/> years
d	Remaining Life of existing refrigerators:	<input type="text" value="0"/> years
e	Cost of electricity:	<input type="text" value="0.132176015"/> \$/kWh
Step 3	Existing Refrigerator Model: <i>GE</i>	
	Approximate annual energy use of each existing refrigerator:	<input type="text" value="850.00"/> kWh/yr
Step 4	Traditional Refrigerator Model: <i>Frigidaire FFTR1515LW</i>	
	Approximate annual energy use of each traditional refrigerator replacement:	<input type="text" value="443.00"/> kWh/yr
Step 5	Green Refrigerator Model: <i>Frigidaire FFHT1515LW (Energy Star)</i>	
	Approximate annual energy use of each old green refrigerator replacement:	<input type="text" value="355.00"/> kWh/yr
Step 6	Calculate Annual Savings vs. Existing Refrigerators:	
	Energy Savings per Unit:	<input type="text" value="850"/> - <input type="text" value="355"/> = <input type="text" value="495"/> kWh/yr
	Total Energy Savings	<input type="text" value="78"/> x <input type="text" value="495"/> = <input type="text" value="38,610"/> kWh/yr
	Total Cost Savings:	<input type="text" value="38610"/> x <input type="text" value="0.13"/> = <input type="text" value="\$5,103.32"/> \$/yr
Step 7	Calculate Annual Savings vs. Traditional Refrigerators:	
	Energy Savings per Unit:	<input type="text" value="443"/> - <input type="text" value="355"/> = <input type="text" value="88"/> kWh/yr
	Total Energy Savings	<input type="text" value="78"/> x <input type="text" value="88"/> = <input type="text" value="6,864"/> kWh/yr
	Total Cost Savings:	<input type="text" value="6864"/> x <input type="text" value="0.13"/> = <input type="text" value="\$907.26"/> \$/yr
Simple Payback Period		
	<input type="text" value="\$45,162"/> / <input type="text" value="\$5,103"/> =	<input type="text" value="8.8"/> years

Energy Conservation Measure

Replace Incandescent Lighting with CFLs in Common Areas

This analysis is for replacement of standard incandescent light bulbs with CFL bulbs in the common areas. The average annual usage and standard replacement bulb size are assumed.

Step 1	Cost Information	
	Cost of installing CFLs (Green)	114.00 \$
	Cost of installing Incandescent (Traditional)	22.80 \$
Step 2	Transfer the following information from the Survey:	
4-13	a Number of incandescent fixtures in common areas:	38
	b Total number of light bulbs to be replaced:	38
	c Average number of hours/day bulbs are in use:	12
5-9	d Cost of electricity:	\$0.13 \$/kWh
Step 3	Lighting Energy Consumption	
	Existing/Traditional Consumption (60 Watt Incandescent)	
	$\frac{0.060}{\text{kW/bulb}} \times \frac{38}{\text{\# of bulbs}} \times \frac{4380}{\text{hrs/year}}$	$= 9986 \text{ kWh/yr}$
	Green Consumption (13 Watt CFL)	
	$\frac{0.013}{\text{kW/bulb}} \times \frac{38}{\text{\# of bulbs}} \times \frac{4380}{\text{hrs/year}}$	$= 2164 \text{ kWh/yr}$
Step 4	Estimate annual energy savings vs. Traditional:	
	$\frac{2a}{9986} - \frac{3}{2164} = \frac{7823}{\text{kWh/yr}}$	
Step 5	Calculate annual cost savings vs. Traditional:	
	$\frac{4}{7822.68} \times \frac{2b}{0.13} = \frac{1033.97}{\text{\$/yr}}$	
	$\frac{114.00}{\text{Cost Differential}} - \frac{22.80}{\text{Cost Savings}} = \frac{91.20}{\text{\$/yr}}$	
Step 6	Calculate payback period:	
	$\frac{1}{114.00} \div \frac{5}{1033.97} = \frac{0.11}{\text{yrs}}$	
	Simple Payback Period	0.11 yrs

Energy Conservation Measure

Replace Fluorescent Fixtures in Common Areas with T-8 Bulbs & Electronic Ballasts

This analysis is for replacement of the T-12 fluorescent lighting with T-8 Lamps and Electronic Ballasts in the common areas. An average annual usage and standard replacement bulb size are assumed.

Step 1	Cost Information	
	Cost of Replacing Fixtures w/ T-8 & Electronic Ballast	13104.00 \$
	Cost of Replacing Fixtures w/ T-12 & Electronic Ballast	10920.00 \$
Step 2	Transfer the following information from the Survey:	
b	Total number of light fixtures to be replaced:	168
c	Existing Watts per bulb	40
d	Number of linear bulbs per fixture	2
e	Average number of hours/day bulbs are in use:	12
f	Cost of electricity:	\$0.13 \$/kWh
Step 3	Lighting Energy Consumption	
	Traditional Consumption <i>T-12 Fluorescent - 40 Watt</i>	
	$\frac{0.040}{\text{kW/bulb}} \times \frac{336}{\text{\# of bulbs}} \times \frac{4380}{\text{hrs/year}} = 58867$	kWh/yr
	Traditional Consumption <i>T-12 Fluorescent - 34 Watt</i>	
	$\frac{0.034}{\text{kW/bulb}} \times \frac{336}{\text{\# of bulbs}} \times \frac{4380}{\text{hrs/year}} = 50037$	kWh/yr
	Green Consumption <i>T-8 Fluorescent - 28 Watt</i>	
	$\frac{0.028}{\text{kW/bulb}} \times \frac{336}{\text{\# of bulbs}} \times \frac{4380}{\text{hrs/year}} = 41207$	kWh/yr
Step 4	Estimate annual energy savings vs. Traditional:	
	$\frac{50037}{2a} - \frac{41207}{3} = 8830$	kWh/yr
Step 5	Calculate annual cost savings vs. Traditional:	
	$\frac{8830.08}{4} \times \frac{0.13}{2b} = 1167.12$	\$/yr
	$\frac{13104.00}{\text{Cost Differential}} - \frac{10920.00}{\text{Cost Savings}} = 2184.00$	\$/yr
Step 6	Calculate payback period:	
	$\frac{13104.00}{1} \div \frac{1167.12}{5} = 11.23$	Simple Payback Period yrs

Energy Conservation Measure

Replace Incandescent Fixtures at Apartment Entry Lights with LED Wall Packs

This analysis is for replacment of the incandescent light bulbs at the apartment entrances with LED wall packs. The average annual usage and existing bulb size are assumed.

Step 1	Cost Information			
	Cost of installing LEDs (Green)	910.00	\$	
	Cost of installing Incandescent (Traditional)	420.00	\$	
Step 2	Transfer the following information from the Survey:			
4-13	a Number of apartment entry lights	14		
	b Total number of light bulbs to be replaced:	14		
	c Average number of hours/day bulbs are in use:	12		
5-9	d Cost of electricity:	\$0.13	\$/kWh	
Step 3	Lighting Energy Consumption			
	Existing/Traditional Consumption (Incandescent)			
	$\frac{0.100}{\text{kW/bulb}} \times \frac{14}{\text{\# of bulbs}} \times \frac{4380}{\text{hrs/year}} = \frac{6132}{\text{kWh/yr}}$			
	Green Consumption (5 Watt LED)			
	$\frac{0.005}{\text{kW/bulb}} \times \frac{14}{\text{\# of bulbs}} \times \frac{4380}{\text{hrs/year}} = \frac{307}{\text{kWh/yr}}$			
Step 4	Estimate annual energy savings vs. Traditional:			
	$\frac{2a}{6132} - \frac{3}{307} = \frac{5825}{\text{kWh/yr}}$			
Step 5	Calcualte annual cost savings vs. Traditional:			
	$\frac{4}{5825.40} \times \frac{2b}{0.13} = \frac{769.98}{\text{\$/yr}}$			
	Cost Savings	5825.40		
	Cost Differential	910.00		
	$\frac{910.00}{420.00} = \frac{490.00}{\text{\$/yr}}$			
Step 6	Calculate payback period:			
	Simple Payback Period	$\frac{910.00}{769.98} = 1.18$		yrs

Energy Conservation Measure**Replace Inefficient Boilers - 2070000 Btu/hr****Step 1** Obtain total cost of replacing the heating plant, including equipment, labor, structural alterations, etc.

\$41,400	\$
----------	----

Step 2 Transfer the following information from the Survey:

a	Regional Annual heating equipment hours:	1,170	hours
b	Input Capacity of Existing Boilers	2,070,000	Btu/hr
c	Number of Boilers	1	
d	Combustion efficiency of existing boilers	72	%
e	Cost of heating fuel:	\$0.61	\$/therm

Natural Gas:

Step 3 Estimate annual energy consumption of Existing Boiler:

Existing Boiler Input Rate:	2070000.00	/	100000.00	=	20.70	therms/hr
Annual Operating Hours:					1,170	hours
Standard Boiler Consumption:					24219	therms
Existing Boiler Ratio to Standard:	80	/	72	=	1.11	
Existing Boiler Consumption:	1.11	x	24219.00	=	26910	therms

Step 4 Estimate annual energy consumption of Condensing Boiler:

	3		2a			
Existing Boiler Output:	26910	x	0.72	=	19375	therms
New Boiler Efficiency:					94	%
New Boiler Input:	19375	/	0.94	=	20612	therms

Step 5 Calculate annual energy and cost savings:

	4		2c			
Energy Saved per Boiler:	26910	-	20612	=	6298	therms
Total Energy Saved:	6298	x	1.00	=	6298	therms
Cost Savings:	6298	x	0.61	=	\$3,839	\$/yr

Step 6 Calculate payback period:

\$41,400	/	\$3,839	=	10.78	yrs
----------	---	---------	---	-------	-----

Energy Conservation Measure
Replace Older PTAC Units with PTHP Units

Step 1	Obtain total cost of replacing existing air conditioners with efficient units:				
	110	PTAC Units	x	\$2,110	per unit
				\$232,100	\$
Step 2	Transfer the following information from the Survey:				
	EER rating of existing PTAC units:		9.0	EER	
	Cooling capacity of existing PTAC units:		14600	Btu/hr	
	Heating capacity of existing PTAC units:		4	kW	
	Number of existing AC units:		110		
	Cost of electricity:		0.132176015	\$/kWh	
Step 3					
	Annual cooling hours		1007	hours	
	Annual heating equipment hours		1170	hours	
	Heat Pump Heating Season Time (%)		33%		
Step 4					
	Existing energy efficiency rating (EER):		9.0		
	Replacement unit EER		11.7		
	Replacement unit coefficient of Performance (COP):		3.4		
	Heat Pump Input Power		4	kW	
			3.4	COP	
			=	1.18	kW
Step 5	Calculate existing energy use per PTAC:				
	Cooling (DX)	Hours	kBtu	EER	
		1007	14.60	9.0	
		x		/	
				=	1634 kWh
	Heating (Resistance)	Hours	kW		
		1170	4.00		
		x		=	4680 kWh
	Total				6314 kWh
Step 6	Calculate energy use per replacement PTHP:				
	Cooling (Heat Pump)	Hours	kBtu	EER	
		1007	14.60	11.7	
		x		/	
				=	1257 kWh
	Heating (Heat Pump)	Hours	%	kW	
		1170	0.33	1.2	
		x		x	
					459 kWh
	Heating (Resistance)	Hours	%	kW	
		1170	0.67	4.0	
		x		x	
					3120 kWh
	Total				4835 kWh
Step 7	Estimate annual energy savings:				
		5	6	2c	
		6314	-	4835	
			x	110.00	
			=	162597	kWh/yr
Step 8	Calculate annual cost savings:				
		7	2d		
		162597	x	0.13	
			=	21491	\$/yr
Step 9	Calculate payback period:				
		1	8		
		232100.00	/	21491.44	
			=	10.80	hrs

Energy Conservation Measure
Replace Newer PTAC Units with PTHP Units

Step 1	Obtain total cost of replacing existing air conditioners with efficient units:				
	20	PTAC Units	x	\$2,110	per unit
				\$42,200	\$
Step 2	Transfer the following information from the Survey:				
	EER rating of existing PTAC units:		11.0	EER	
	Cooling capacity of existing PTAC units:		14600	Btu/hr	
	Heating capacity of existing PTAC units:		4	kW	
	Number of existing AC units:		20		
	Cost of electricity:		0.132176015	\$/kWh	
Step 3					
	Annual cooling hours		1007	hours	
	Annual heating equipment hours		1170	hours	
	Heat Pump Heating Season Time (%)		33%		
Step 4					
	Existing energy efficiency ratio:		11.0	EER	
	Replacement unit energy efficiency ratio:		11.7	EER	
	Replacement unit Coefficient of Performance:		3.4	COP	
	Heat Pump Input Power	4	/	3.4	= 1.18 kW
Step 5	Calculate existing energy use per PTAC:				
Cooling (DX)	Hours	1007	x	kBtu	14.60
			/	EER	11.0
			=	1337	kWh
Heating (Resistance)	Hours	1170	x	kW	4.00
			=	4680	kWh
Total				6017	kWh
Step 6	Calculate energy use per replacement PTHP:				
Cooling (Heat Pump)	Hours	1007	x	kBtu	14.60
			/	EER	11.7
			=	1257	kWh
Heating (Heat Pump)	Hours	1170	x	%	0.33
			x	kW	1.2
				459	kWh
Heating (Resistance)	Hours	1170	x	%	0.67
			x	kW	4.0
				3120	kWh
Total				4835	kWh
Step 7	Estimate annual energy savings:				
	5	6	2c		
	6017	-	4835	x	20.00
				=	23623 kWh/yr
Step 8	Calculate annual cost savings:				
	7	2d			
	23623	x	0.13	=	3122 \$/yr
Step 9	Calculate payback period:				
	1	8			
	42200.00	/	3122.37	=	13.52 yrs

Energy Conservation Measure

Replace Older Plumbing Fixtures with Low Flow Devices

Input Data:

Step 1	Number of residents	145			
	Total annual use days	365			
		Water closet	Sinks	Shower	
	Existing water controls in gallons per use	3.5	2	2.5	
	low -flow water controls in gallons per use	1.6	1.5	2	
	Low-flow replacement cost	\$320.00	\$4.00	\$75.00	
Step 2		Quantity	Daily Usage Assumption		
	Total number of old water closets	130	4.5	flushes	
	Total number of sinks to be upgraded	130	6.0	minutes	
	Total number of shower heads to be upgraded	130	11.2	minutes	
	Total Water Rate	\$ 0.0064 /gal			
Step 3		Calculations:			
	Water conservation method	Total to be replaced	Cost of replacement	Total cost	
	Replace existing with low flow water closets	130	\$320	\$41,600.00	
	Install aerators on existing faucet controls	130	\$4	\$520.00	
	Replace existing shower heads	130	\$75	\$9,750.00	
			Total	\$51,870.00	
	Results				
	Annual Savings	Annual time used	Gallons saved	Annual cost savings	Payback
	Annual water closet flushes (flushes)	211,700	402,230	\$2,583.73	16.10075867
	Annual sink use (minutes)	284,700	142,350	\$914.39	0.568687053
	Annual shower use (minutes)	529,250	264,625	\$1,699.82	5.735895277
		Total	809,205	\$5,197.94	
	Simple Payback		9.98 years		