

An aerial photograph showing a two-lane road bridge crossing a body of water. The bridge is a simple beam bridge with concrete supports. The water is dark green, and the surrounding land is a mix of green grass and brown patches. A large teal rectangle is overlaid on the top left of the image, containing the title text in white.

# **GROTON LONG POINT ROAD BRIDGE OVER PALMER'S COVE**

## **GROTON LONG POINT ROAD BRIDGE STRUCTURE TYPE STUDY REPORT**

Groton, Connecticut

Presentation By:  
James A. Platosh, P.E.

September 22, 2015



Town of Groton Department of Public Works

**AECOM**

# **PRESENTATION OVERVIEW**

## **Groton Long Point Road Bridge Over Palmer's Cove**

- **Background – October 2013 Presentation of Bridge Study Final Report**
- **Presentation of Aug. 2015 Structure Type Study Report**
  - **Alternative Bridge Types Considered**
  - **Causeway Stability**
  - **Roadway Project Limits**
  - **Location of Sidewalk**
  - **Relocation of Overhead Utilities**
  - **Bridge Vertical Clearance**
  - **Federal Funding Opportunity**



# PROJECT AREA



# GROTON LONG POINT ROAD BRIDGE





# ROADWAY RECONSTRUCTION LIMITS





# THE FUTURE OF THE GROTON LONG POINT ROAD BRIDGE OVER PALMER'S COVE

## GROTON LONG POINT ROAD BRIDGE STUDY FINAL REPORT

Groton, Connecticut

Presentation By:  
James A. Platosh, P.E.

October 22, 2013



Town of Groton Department of Public Works

**URS**



# DID YOU VISIT US ONLINE?

Visit the website:  
[GrotonLongPointBridge.com](http://GrotonLongPointBridge.com)



Follow us on Facebook!




“We want to hear from you!”

# BACKGROUND

## Public Meeting No. 1

August 30, 2012

5:00 to 8:00pm




THE FUTURE OF THE GROTON LONG POINT ROAD BRIDGE  
OVER PALMER'S COVE

August 30, 2012 | 5pm to 8pm  
TOWN HALL ANNEX COMMUNITY ROOM #1  
134 GROTON LONG POINT ROAD, GROTON, CT 06340-4873

# PUBLIC LISTENING SESSION

Meeting Purpose: Solicit your ideas & input concerning the  
rehabilitation or replacement of the Groton Long Point Road Bridge  
"We want to hear from you!"

 Town of Groton Department of Public Works

The poster features an aerial photograph of the bridge and surrounding area. At the bottom, there are three small photographs: the left one shows a view of the bridge from the water; the middle one shows a view of the bridge from the road; the right one shows a view of the road and the bridge from a distance.



# COMMENTS

## ■ Boater Concerns

- Vertical Clearance
- Horizontal Clearance
- Dredge Channel
- Maintain Access Between March and November and During Construction



## ■ Bridge User Concerns

- Widened for Bicycles and Pedestrians Safely
- Walkway for Pedestrians
- Children Jumping from Bridge
- Fishing Platform
- Water Main on Bridge is Back-up for Groton Long Point

# COMMENTS CONTINUED...

## ■ Environmental Concerns

- Increase Tidal Flow
- Sediment Accumulation Causing Sand Bar
- Withstand Major Hurricanes
- Protect Homeowners Adjacent
- Only Route Off Point in Emergency



## ■ Timing

- Accident Waiting to Happen
- Repaired ASAP




# SCOPE OF WORK

*Prepare Engineering Investigation and Evaluation of Rehabilitation Options for Bridge and Causeway.*



# STUDY OBJECTIVES

-  Provide Safe Bridge Crossing and Roadway for Vehicles and Pedestrians
-  Provide Causeway Capable of Withstanding Storm Surge
-  Provide Structure that is Economical to Build and Maintain
-  Minimize Environmental Impacts of Project
-  Provide an Aesthetically Pleasing Structure that Complements the Area



# **EXISTING ROAD AND BRIDGE CONDITIONS**



**Bridge and Causeway Built  
in 1935**



**30' Roadway**



- **Wire Rope Guide Rail**
  - Substandard, poor condition
  - Not connected to bridge parapets
  - Minimal embedment due to erosion



**EXISTING  
ROADWAY**

## ■ Superstructure

- Concrete Encased Steel Beams
- Cast-in-Place Concrete Deck
- Abutments and Flared Wingwalls with Stone Veneer
- Supported on Wood Piles
- Concrete Parapets



**EXISTING  
BRIDGE**



# UTILITIES

- Overhead Utilities
  - Electrical Feed to Fishers Island
- Watermain
- Sanitary Sewer Force Main



# COMBINED UNDERWATER AND IN-DEPTH INSPECTION



BRIDGE NO. 04675  
GROTON LONG POINT ROAD OVER PALMER COVE  
GROTON, CONNECTICUT  
SEPTEMBER 7, 2012

## BRIDGE SAFETY INSPECTION STATE PROJECT NO. 170-2868



Prepared by:



45 Barberry Lane, Meriden, CT 06457  
100 Snake Hill Road, West Nyack, NY 10994



2096A Silas Deane Hwy  
Rocky Hill, CT. 06067

# CTDOT

SEPTEMBER 7, 2012  
IN-DEPTH &  
UNDERWATER  
INSPECTION  
RESULTS



Executive Summary

Bridge No. 04674 carries Groton Long Point Road over Palmer Cove in Groton. The single-span concrete encased steel multi-girder bridge with reinforced concrete deck was built in 1935, has an overall length of 56 feet and a curb-to-curb width of 30 feet. Stone masonry abutments support the superstructure. Palmer Cove is a salt water body with tidal flow. According to the information on file with the Connecticut Department of Transportation, the Inventory rating for an H-20 loading is 75 tons using composite action between the deck and girders. Due to the separation between the deck and beams, the previous load rating should be updated analyzing the bridge as a non-composite structure.

A combined underwater and in-depth inspection was started on September 7, 2012 and completed on September 12, 2012 and found the bridge to be in poor condition (overall rating = 4). The deficiencies found on the bridge and recommendations for repairs are as follows:

Deck:

The deck is in poor condition (Overall rating = 4) due to the following:

1. Approximately 50% of the bituminous concrete overlay has hollow areas with map cracks and areas of concrete pumping through cracks. There is a bituminous patch in eastbound lane over the East Abutment. Seal the cracks (400 LF).
2. The deck ends over the abutments have random transverse cracks up to full length, raveling areas up to 1 ft. by 3 in. by 1 in. deep, minor uneven areas, bituminous patches and spalls. Repair overlay and/or joint detail at deck ends (40 LF).
3. The underside of the concrete deck has random transverse hairline cracks with isolated dampness and efflorescence, and extensive areas of hairline map cracking with dampness and/or efflorescence. There are random hollow areas and spalls along the underside of the deck overhangs adjacent to the fascia girders up to 10 ft. long by 10 in. wide and up to 1 in. deep. Both deck ends over the abutments are spalled up to full length by 4 in. wide by 3 in. deep with random areas of exposed reinforcement. There is up to a 3/8 in. gap by 10 ft. long between the top of all girders and the deck overhang for full length. The total underside of deck deterioration is approximately 43.4%. Continue to monitor.
4. There are free fall drain pipes at all four corners of the bridge. The northeast, northwest and southeast pipes are fully clogged with dirt, and the end 6 in. of the drain pipes have up to 100% loss. Clean out drain pipes (3 EA).

Superstructure:

The superstructure is in poor condition (Overall rating = 4) due to the following:

1. Steel sliding plates at both abutments have light to moderate rust with random areas of painted over laminated rust and pack rust between plates up to 1 inch thick. West Abutment bearing plates have random areas of pitting up to 1/4 in. deep. No evidence of movement. Continue to monitor.
2. The bottom flanges at the bearing areas have as little as 3/4 in. remaining at the edge of the flange for up to 1 in. wide at both sides along the bearing plates (1 1/4 in. original, 2.7% loss in non

**CTDOT  
BRIDGE****SAFETY INSPECTION**  
September 7, 2012

*“...found the **Bridge** to be in poor condition (Overall Rating = 4)...”*

*“...The **Deck** is in poor condition (Overall Rating = 4)...”*

*“...The **Superstructure** is in poor condition (Overall Rating = 4)...”*



critical zone). The remaining flange length has spotty areas of 1/8 in. deep pitting (< 5% loss). The concrete encasement has random cracks and hollow areas/spalls along the webs, up to full length by 1 ft. high by 1 in. deep, and along the haunches of the top flanges, up to full length by 8 in. wide by 2 in. deep. The top flange edges have laminated rust and up to 1/16 in. loss of width where exposed. There is laminated rust along the bottom flange edges with up to 1/16 in. loss of width.

**Substructure:**

The substructure is in fair condition (Overall rating = 5) due to the following:

1. There are random vertical and transverse hairline cracks in the concrete abutment caps with rust stains. The West Abutment has hollow areas under G5 & G6, 6 square feet total. Also, hollow areas extend along the side of bearings with heavy scale areas ½ in. deep. The stone masonry has random hairline cracks in the mortar joints. Continue to monitor.
2. The concrete wingwall caps have hairline map cracking throughout and several random vertical and transverse cracks up to ½ in. wide. Stems have random displaced stones. All four wingwalls have spalls near the ends of the walls up to 4 ft. long by 0.9 ft. high by 0.8 ft. deep. The caps are typically displaced at these spall locations, up to 1½ in. (all wingwalls except northwest). The stone masonry has up to 20% of loose/missing mortar along the joints with up to 1.5 ft. of penetration. The northwest wingwall has a ¼ in. wide by up to 6 ft. high vertical crack adjacent to the abutment stem. Repair deteriorated concrete along the caps (1 CY).

**Channel and Channel Protection:**

The channel is in satisfactory condition (Overall rating = 6) due to the following:

1. The mudline along the West Abutment has typically lowered up to 0.9 ft. and there is up to 1.2 ft. of degradation along the northwest wingwall since the 2008 inspection. The mudline along the East Abutment has typically lowered up to 0.5 ft. since the 2008 inspection. The mudline along the north fascia has lowered up to 0.9 ft. and has risen up to 0.7 ft. since the 2008 inspection. Continue to monitor.

**Approach Condition:**

The approach is in fair condition (Overall rating = 5, downrated from 6) due to the following:

1. The cables of the approach guide rails are typically slack, the timber posts are typically weathered and random posts are leaning/tilted. One post at the southeast approach is snapped off at ground level. Consider installing an improved guide rail system.
2. Both approach pavements have random longitudinal and transverse cracks. The pavement along the deck ends is breaking up with random areas of raveling, and is settled up to 2 in. (worst locations are in the north shoulder over the East Abutment). Seal the cracks (100± LF) and repair potholes and settlement (<½ TON).
3. There is an 8 in. diameter by 1 ft. deep erosion area at the northwest embankment adjacent to the first timber guard rail post, and a 10 ft. by 3 ft. by up to 1 ft. deep erosion area along the southwest embankment. Repair erosion areas (1 CY).

# CTDOT BRIDGE SAFETY INSPECTION September 7, 2012


***“...The Substructure is in fair condition  
(Overall Rating = 5)...”***

***“...The Channel is in satisfactory condition  
(Overall Rating = 6)...”***

***“...The Approach is in fair condition (Overall Rating = 5,  
downrated from 6)...”***

# CONDITIONS OF EXISTING BRIDGE

- Last inspected by CTDOT: September 7, 2012
- Deck
  - Roadway surface – Cracking at joints
  - Underside of deck – Extensive map cracking
  - Rated: 4





# CONDITIONS OF EXISTING BRIDGE

## ■ Superstructure

- Concrete encased beams
- Rated: 4





# CONDITIONS OF EXISTING BRIDGE

- Substructure

- Rated: 5

- Overall Condition:

- *Poor*



# CONDITIONS OF EXISTING CAUSEWAY

## ■ Causeway

- Randomly Placed Stone of Various Sizes
- Brush, Small Trees
- Sand Below High Tide Line





# HURRICANE DAMAGE ASSESSMENT

Town Engineering Division

## Hurricane Sandy Preliminary Damage Assessment Report

- Struck October 29, 2012
- No observable movement, cracking or shifting of substructure, substructure or roadway surface
- Eroded along edge of roadway on southern bank of causeway





# HURRICANE DAMAGE ASSESSMENT

Town Engineering Division

## Hurricane Sandy Preliminary Damage Assessment Report



- Water over-topped roadway in low profile area west of bridge

# HURRICANE DAMAGE ASSESSMENT

Town Engineering Division

## Hurricane Sandy Preliminary Damage Assessment Report

- Eastbound lane closed to traffic
- Roadway Elevations
  - Center of Bridge: Elevation 9.30
  - Roadway Low Point (240' West of Bridge): Elevation 7.96





# NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION (NOAA) TIDE DATA

- New London Gauging Station
- Water level peaked October, 29, 2012 at 8:12pm
  - Water level peak: Elevation: 6.16
- Bridge Bottom Chord Elevation: Elevation 5.72
- Supports evidence wave action over-topped roadway
- From 7:48 PM to 8:54 PM
  - Water Level: Elevation 6.0
- From 6:00 PM to 10:36 PM
  - Water Level: Elevation 5.0





# **PROPOSED BRIDGE REHABILITATION ALTERNATIVES**

# OVERVIEW

**Bridge  
Rehabilitation**

**Alternative  
No. 1**

**Superstructure  
Replacement**

**Alternative  
No. 2**

**Superstructure  
Replacement with  
Pedestrian Bridge**

**Bridge  
Replacement**

**Alternative  
No. 3**

**Bridge Replacement  
Single Span**

**Alternative  
No. 4**

**Bridge Replacement  
Three Span**

# BASIS OF ALTERNATIVE STRUCTURE TYPE SELECTION

- Must accommodate staged construction to maintain vehicular traffic flow
- Must be durable in coastal environment
- Must be economical to build and maintain
- Separate permanent or temporary pedestrian bridge is required to maintain pedestrian traffic during construction
- Reuse of some structural elements considered for reasons of economy
- Rehabilitation of existing superstructure considered deemed impractical and uneconomical





Roadway	30'
Travel Lanes	12'
Shoulders/Bike Lane	3'
Pedestrian Accommodations	None

**EXISTING  
ROADWAY**



Roadway	33'
Travel Lanes	12'
Shoulders/Bike Lane	4' 6"
Pedestrian Accommodations	None

## ALTERNATIVE NO. 1

Superstructure  
Replacement





Roadway	33'
Travel Lanes	12'
Shoulders/Bike Lane	4' 6"
Pedestrian Accommodations	6' Pedestrian Bridge

## ALTERNATIVE NO.2

Superstructure  
Replacement  
with Sidewalk





Roadway	33'
Travel Lanes	12'
Shoulders/Bike Lane	4' 6"
Pedestrian Accommodations	6' Sidewalk

## ALTERNATIVE NO.3

Bridge  
Replacement  
and Widening





EXISTING

URS





ALTERNATIVE NO.1 -SUPERSTRUCTURE  
REPLACEMENT

URS





ALTERNATIVE NO.2 - SUPERSTRUCTURE  
REPLACEMENT WITH SIDEWALK





**ALTERNATIVE NO.3 - BRIDGE  
REPLACEMENT AND WIDENING**

**URS**





EXISTING

URS





ALTERNATIVE NO.1 -SUPERSTRUCTURE  
REPLACEMENT

URS



ALTERNATIVE NO.2 - SUPERSTRUCTURE  
REPLACEMENT WITH SIDEWALK

URS





**ALTERNATIVE NO.3 - BRIDGE  
REPLACEMENT AND WIDENING**

**URS**





EXISTING

URS





ALTERNATIVE NO.1 -SUPERSTRUCTURE  
REPLACEMENT





ALTERNATIVE NO.2 - SUPERSTRUCTURE  
REPLACEMENT WITH SIDEWALK

URS





ALTERNATIVE NO.3 - BRIDGE  
REPLACEMENT AND WIDENING

URS

# SUMMARY

## ALTERNATIVE NO. 1 – Superstructure Replacement

Roadway	33'
Travel Lanes	12'
Shoulders	4' 6"
Pedestrian Accommodations	None

## ALTERNATIVE NO. 2 – Superstructure Replacement with Sidewalk

Roadway	33'
Travel Lanes	12'
Shoulders	4' 6"
Pedestrian Accommodations	6' Pedestrian Bridge

## ALTERNATIVE NO. 3 – Bridge Replacement with Widening and Sidewalk

Roadway	33'
Travel Lanes	12'
Shoulders	4' 6"
Pedestrian Accommodations	6' Sidewalk

## ALTERNATIVE NO. 4 – *Full Replacement* *3 Spans, 36'-86'-36'*

Roadway	33'
Travel Lanes	12'
Shoulders	4' 6"
Pedestrian Accommodations	6' Sidewalk



# CONSTRUCTION COST SUMMARY

## Bridge Alternatives

**ALTERNATIVE  
NO. 1 -  
Superstructure  
Replacement**

**\$1,700,000**

**ALTERNATIVE  
NO. 2 -  
Superstructure  
Replacement with  
Sidewalk**

**\$2,400,000**

**ALTERNATIVE  
NO. 3 - Bridge  
Replacement and  
Widening**

**\$4,100,000+**

**ALTERNATIVE  
NO. 4 - Full Bridge  
Replacement**

**\$5,400,000+**

# PROPOSED CAUSEWAY REHABILITATION ALTERNATIVES

## Alternative A

Placement of Additional  
Protective Stone Armoring

## Alternative B

Pile Support Retaining Wall





# CONSTRUCTION COST SUMMARY



## Causeway Options

**ALTERNATIVE A –  
Protective Armoring**

**\$500,000**

**ALTERNATIVE B – Pile  
Supported Retaining Wall  
to Support Widened  
Roadway**

**\$1,000,000**




URS

Figure 2

Existing Bridge

General Plan & Elevation






**TYPICAL SECTION**  
SCALE: 3/16" = 1'-0"

**URS**


**Figure 3**

**Existing Bridge**

**Typical Section**








**TYPICAL SECTION**  
SCALE: 3/16" = 1'-0"

**Figure 5**


**Alternative No. 1**  
**Superstructure Replacement**

**Typical Section**


**URS**




STAGE 1A



STAGE 2A



STAGE 1B



STAGE 2B

STAGE CONSTRUCTION  
SCALE: 1/8" = 1'-0"


URS


Figure 6

Alternative No. 1  
Superstructure Replacement

Stage Construction







**TYPICAL SECTION**  
SCALE: 3/16" = 1'-0"


**URS**

**Figure 8**


**Alternative No. 2  
Superstructure Replacement  
and Pedestrian Bridge**

**Typical Section**







STAGE 1A



STAGE 2A



STAGE 1B



STAGE 2B


STAGE CONSTRUCTION  
SCALE: 1/8" = 1'-0"

URS

Figure 9


Alternative No. 2  
Superstructure Replacement  
and Pedestrian Bridge

Stage Construction












STAGE 1A



STAGE 2A



STAGE 1B




STAGE 2B

STAGE CONSTRUCTION  
SCALE: 1/8" = 1'-0"

URS

Figure 12  
Alternative No. 3  
Complete Replacement  
with Single-Span Bridge  
Stage Construction




**Figure 13**


**Alternative No. 4  
Complete Replacement  
with Three-Span Bridge**

**General Plan & Elevation**

**URS**








**TYPICAL SECTION**  
SCALE: 3/16" = 1'-0"

**URS**


**Figure 14**

**Alternative No. 4  
Complete Replacement  
with Three-Span Bridge**


**Typical Section**




STAGE 1A



STAGE 2A



STAGE 1B



STAGE 2B

STAGE CONSTRUCTION  
SCALE: 1/8" = 1'-0"

URS

Figure 15  
Alternative No. 4  
Complete Replacement  
with Three-Span Bridge  
Stage Construction



# **CONSTRUCTION STAGING**

# CONSTRUCTION STAGING

***Objective: Maintain  
vehicular,  
pedestrian, and  
marine traffic flow***

**Construct Pedestrian Bridge and Walkway**

**Install Temporary Traffic Signal**

**Implement Alternating Traffic Flow**

**Construction Stage 1 - Southerly Half of Bridge**

**Open Completed Half to Traffic**

**Construct Stage 2 - Northerly Half of Bridge**

**Open New Bridge to Traffic**



**STAGE 1**





**STAGE 2**

# CONSTRUCTION SCHEDULE

- Driven by Environmental Permit Restrictions
- Stage 1
  - First Season
- Stage 2
  - Second Season



# OPEN DISCUSSION AND QUESTIONS & ANSWERS

Visit the website:

**GrotonLongPointBridge.com**



Follow us on Facebook



***“We want to hear from you!”***



Town of Groton Department of Public Works

**URS**



An aerial photograph showing a two-lane road bridge crossing a body of water. The bridge is a simple beam bridge with a concrete deck. On the right side of the road, there is a building and some parking areas. The water is dark, and the shoreline is visible with some rocks and vegetation.

# **GROTON LONG POINT ROAD BRIDGE OVER PALMER'S COVE**

## **GROTON LONG POINT ROAD BRIDGE STRUCTURE TYPE STUDY REPORT**

Groton, Connecticut

Presentation By:  
James A. Platosh, P.E.

September 22, 2015



Town of Groton Department of Public Works

**AECOM**



# PROJECT AREA



# GROTON LONG POINT ROAD BRIDGE






# ROADWAY RECONSTRUCTION LIMITS



# STRUCTURE TYPE STUDY REPORT

## COMPLETED AUGUST 2015



### ■ Evaluated

- (3) roadway structure type options
- (3) pedestrian structure type option
- Causeway stability analysis

# ALTERNATIVE BRIDGE TYPES CONSIDERED

- **Superstructure Replacement Alternatives**
  - Alternative SR1, Prestressed Concrete Box Beams
  - Alternative SR2, Steel Rolled Beams
  - Alternative SR3, NEXT Beams
  
- **Pedestrian Bridge Alternatives**
  - Alternative PB1, Prestressed Concrete Box Beams
  - Alternative PB2, Steel Rolled Beams
  - Alternative PB3, Prefabricated Half Through Truss



# CONSTRUCTION COST

- **Superstructure Replacement Alternatives**
  - Alternative SR1, Prestressed Concrete Box Beams - **\$898,000**
  - Alternative SR2, Steel Rolled Beams - **\$973,000**
  - Alternative SR3, NEXT Beams - **\$927,000**
- **Pedestrian Bridge Alternatives**
  - Alternative PB1, Prestressed Concrete Box Beams - **\$417,000**
  - Alternative PB2, Steel Rolled Beams - **\$491,000**
  - Alternative PB3, Prefabricated Half Through Truss - **\$378,000**
- **Cost Differences between Alternatives are Negligible**

# ROADWAY RECONSTRUCTION

- **Maintain essentially same width within 60 R.O.W.**
  - Start at Fisherman Restaurant
  - End at East Shore Drive
- **Provide sidewalk on one side**
  - Need further study to determine North or South side
- **Maintain essentially same profile grade on approaches**
  - Grade at bridge about 1 foot higher





EXISTING

URS



# UTILITIES

- Relocate Overhead Utilities

- Electrical
- Telephone
- Cable



- Relocate Watermain to New Bridge



# CAUSEWAY

- Existing constructed after Hurricane Carol (1954)
- Revetment comprised of large riprap (stones with dimensions of 4-5 feet)
- Withstood numerous major storms since construction
  - Numerous Nor'easters
  - Tropical Storm Irene (2011)
  - Remnants of Hurricane Sandy (2012 – Storm of Record)
- Minor damage reported
- Revetment will be reconstructed to support widened roadway



# CAUSEWAY (CONTINUED)

- New revetment designed according to state-of-the-art Federal Highway guidelines and procedures
- New revetment will comprise well-graded riprap of approximately the same size
- Designed with top and toe embedment
- New design considers projected sea level rise
  - 10" of the next 100 years





# FUNDING OPTION

**CONNECTICUT  
DEPARTMENT OF TRANSPORTATION**

## **LOCAL BRIDGE PROGRAM**

*Fiscal Year 2016*



*THE HONORABLE DANIEL P. MALLOY,  
GOVERNOR*

*JAMES REDEKER,  
COMMISSIONER*

- Federal Funds
- HBP / Off System Bridge STP
- Reimbursement
  - Federal – 80%
  - Town – 20%

# FEDERAL FUNDING

- Eligible Costs
- Preliminary Engineering
  - Advertising for consulting engineer selection (RFQ/RFPs, etc.)
  - Engineering studies and inspections undertaken to determine whether a bridge is eligible for the Local Bridge Program
  - Preliminary surveys
  - Preliminary engineering activities, including type studies, preparation of project plans, specifications, and cost estimates
  - Preparation of bid documents
  - Preparation of permit applications
  - Soil borings and other subsurface investigations used for design
  - Public hearings and legal notices
  - Historical reviews and archeological studies prior to construction

# FEDERAL FUNDING (CONTINUED)

- **Rights of Way**
  - Property and easement acquisition
  - Property appraisals
  - Title searches
  - Legal fees for eminent domain proceedings
- **Utilities**
- **Construction**
  - Construction costs
  - Temporary structures necessary to perform the work
  - Payroll costs of municipal employees directly working on the project
  - Costs generally recognized as reasonable and necessary for the performance of the project taking
  - Costs incurred to comply with Federal and State laws and regulations



# FEDERAL FUNDING (CONTINUED)

- **Construction Engineering / Incidentals to Construction**
  - Construction inspection
  - Materials testing
  - Construction advertising
  - Construction bid review and analysis
  - Review of shop, construction and working drawings
  - Engineering support and consultation during construction
  - Inspector's field office costs
  - Archeological studies after beginning construction
  - Construction staking and surveying not performed by the construction contractor
  - Other costs generally recognized as reasonable and necessary for the performance of the project to the standards used on CTDOT projects

# NEXT STEPS


- Advance bridge design
- Establish roadway profile
- Design roadway reconstruction
  - Confirm project limits
- Determine sidewalk location
- Design causeway stability
- Determine project funding




# OPEN DISCUSSION AND QUESTIONS & ANSWERS







AECOM





**TYPICAL SECTION**  
SCALE: 3/16" = 1'-0"

**AECOM**


*Figure X*


*Existing Bridge*





*Typical Section*












**STAGE CONSTRUCTION**  
SCALE: 1/4" = 1'-0"

**AECOM**

**Figure X**  
**Alternative No. 1**  
**Prestressed Concrete Box Beam**  
**Vehicular Bridge**  
**Stage Construction**





NOTE:

APPROXIMATE VEHICULAR BRIDGE DEPTH IS 3.50 FEET (MEASURED FROM POINT OF APPLICATION OF GRADE TO THE BOTTOM OF LOW CHORD ELEVATION).

**TYPICAL SECTION**  
SCALE: 3/16" = 1'-0"

**AECOM**





*Figure X*

*Alternative No. 1  
Prestressed Concrete Box Beam  
Vehicular Bridge*

*Typical Section*



### General Plan & Elevation



**STAGE CONSTRUCTION**  
SCALE: 1/2" = 1'-0"


**AECOM**

*Figure X*

*Alternative No. 2  
Rolled Beam  
Vehicular Bridge*

*Stage Construction*





NOTE:

APPROXIMATE VEHICULAR BRIDGE DEPTH IS 3.43 FEET (MEASURED FROM POINT OF APPLICATION OF GRADE TO THE BOTTOM OF LOW CHORD ELEVATION).


**TYPICAL SECTION**  
SCALE: 3/16" = 1'-0"

**AECOM**





*Figure X*

*Alternative No. 2  
Rolled Beam  
Vehicular Bridge*

*Typical Section*



AECOM



**STAGE CONSTRUCTION**  
SCALE: 1/4" = 1'-0"


**AECOM**

*Figure X*

*Alternative No. 2  
Rolled Beam  
Vehicular Bridge*

*Stage Construction*





NOTE:

APPROXIMATE VEHICULAR BRIDGE DEPTH IS 3.86 FEET (MEASURED FROM POINT OF APPLICATION OF GRADE TO THE BOTTOM OF LOW CHORD ELEVATION).

**TYPICAL SECTION**


SCALE: 3/16" = 1'-0"

**AECOM**

*Figure X*

*Alternative No. 3  
NEXT Beam  
Vehicular Bridge*

*Typical Section*




NOTE:

APPROXIMATE PEDESTRIAN BRIDGE DEPTH IS 4.125 FEET (MEASURED FROM POINT OF APPLICATION OF GRADE TO THE BOTTOM OF LOW CHORD ELEVATION).

### ALTERNATIVE 1: BOX BEAM - ELEVATION

SCALE: 1" = 10'




NOTE:

APPROXIMATE PEDESTRIAN BRIDGE DEPTH IS 4.22 FEET (MEASURED FROM POINT OF APPLICATION OF GRADE TO THE BOTTOM OF LOW CHORD ELEVATION).

### ALTERNATIVE 2: ROLLED BEAM - ELEVATION

SCALE: 1" = 10'




NOTE:

APPROXIMATE PEDESTRIAN BRIDGE DEPTH IS 2 FEET (MEASURED FROM POINT OF APPLICATION OF GRADE TO THE BOTTOM OF LOW CHORD ELEVATION).


### ALTERNATIVE 3: PONY THRU PREFABRICATED TRUSS - ELEVATION

SCALE: 1" = 10'




### TYPICAL SECTION

SCALE: 3/16" = 1'-0"



### TYPICAL SECTION

SCALE: 3/16" = 1'-0"



### TYPICAL SECTION


SCALE: 3/16" = 1'-0"

Figure X

Pedestrian Bridge Alternatives

Bridge Sections and Elevations

AECOM



**TYPICAL SECTION**  
SCALE: 3/16" = 1'-0"

**AECOM**

*Figure X*

*Existing Bridge*

*Typical Section*