

Inspection Findings

| Date | Building | Unit | Tenant | Housing Code Violation | Room/Area | Agency |
|----------|----------|------|-------------------------|-------------------------------------|-------------|--------|
| | | 10 | 147 Williams, Christine | mold/environmental review pending | Unit | LLHD |
| 9/6/2022 | | 10 | 147 Williams, Christine | peeling paint | stairs | City |
| 9/6/2022 | | 10 | 147 Williams, Christine | peeling paint | hall | City |
| 9/6/2022 | | 10 | 147 Williams, Christine | peeling paint | basement | City |
| 9/6/2022 | | 10 | 147 Williams, Christine | sewer pipe improperly repaired | Unit | City |
| 9/6/2022 | | 14 | 175 Gonzalez, Wilmarie | cold air, corner cabinet | kitchen | City |
| 9/6/2022 | | 14 | 175 Gonzalez, Wilmarie | face plate taped to wall | Unit | City |
| 9/6/2022 | | 14 | 175 Gonzalez, Wilmarie | leak, water into electrical fixture | dining room | City |
| | | 14 | 175 Gonzalez, Wilmarie | mold/environmental review pending | Unit | LLHD |
| 9/6/2022 | | 14 | 175 Gonzalez, Wilmarie | peeling paint | dining room | City |
| 9/6/2022 | | 14 | 175 Gonzalez, Wilmarie | rodents | Unit | City |
| 9/6/2022 | | 14 | 175 Gonzalez, Wilmarie | stairs - cracked | stairs | City |
| 9/6/2022 | | 14 | 181 Monsegur, Maria | cockroaches and termites | Unit | City |
| 9/6/2022 | | 14 | 181 Monsegur, Maria | fan not clean | bathroom | City |
| 9/6/2022 | | 14 | 181 Monsegur, Maria | fan not working | crawl space | City |
| | | 14 | 181 Monsegur, Maria | mold/environmental review pending | Unit | LLHD |
| 9/6/2022 | | 14 | 181 Monsegur, Maria | pipes broken | crawl space | City |
| 9/6/2022 | | 18 | 159 Levy, Valarie | electrical panel - painted shut | hall | City |
| 9/6/2022 | | 18 | 159 Levy, Valarie | floor buckling | bedroom | City |
| 9/6/2022 | | 18 | 159 Levy, Valarie | floor buckling | bathroom | City |
| 9/6/2022 | | 18 | 159 Levy, Valarie | insulation falling | crawl space | City |
| 9/6/2022 | | 18 | 159 Levy, Valarie | lack of vapor barrier | crawl space | City |
| 9/6/2022 | | 18 | 159 Levy, Valarie | moisture | crawl space | City |
| | | 18 | 159 Levy, Valarie | mold/environmental review pending | Unit | LLHD |
| 9/6/2022 | | 18 | 159 Levy, Valarie | nail pops, ceiling | bathroom | City |
| 9/6/2022 | | 18 | 159 Levy, Valarie | peeling paint | bedroom | City |
| | | 19 | 139 Barreras, Fenilda | mold/environmental review pending | Unit | LLHD |
| 9/6/2022 | | 19 | 139 Barreras, Fenilda | mouse droppings | Unit | City |
| 9/6/2022 | | 19 | 139 Barreras, Fenilda | peeling paint | Unit | City |
| 9/6/2022 | | 32 | 38 Stovall, Abigail | baluster- stair | stairs | City |
| 9/6/2022 | | 32 | 38 Stovall, Abigail | baseboard, damaged | Unit | City |
| 9/6/2022 | | 32 | 38 Stovall, Abigail | dishwasher leak | kitchen | City |
| 9/6/2022 | | 32 | 38 Stovall, Abigail | handrail split | stairs | City |
| | | 32 | 38 Stovall, Abigail | mold/environmental review pending | Unit | LLHD |
| 9/6/2022 | | 32 | 38 Stovall, Abigail | sewer pipe improperly repaired | basement | City |
| 9/6/2022 | | 32 | 38 Stovall, Abigail | smoke detector removed | living room | City |
| 9/6/2022 | | 32 | 38 Stovall, Abigail | smoke detector removed | hall | City |

Inspection Findings

| | | | | | |
|----------|----|-------------------------|---------------------------------------|-------------|------|
| 9/6/2022 | 32 | 44 Ramos, Ramonita | bathtub unsealed | bathroom | City |
| 9/6/2022 | 32 | 44 Ramos, Ramonita | electrical GFCI in kitchen | kitchen | City |
| 9/6/2022 | 32 | 44 Ramos, Ramonita | electrical not supported - basement | basement | City |
| 9/6/2022 | 32 | 44 Ramos, Ramonita | kitchen sink | kitchen | City |
| | 32 | 44 Ramos, Ramonita | mold/environmental review pending | Unit | LLHD |
| 9/6/2022 | 32 | 44 Ramos, Ramonita | peeling paint - stairway | stairs | City |
| 9/6/2022 | 32 | 44 Ramos, Ramonita | shower valve loose in wall | bathroom | City |
| 9/6/2022 | 32 | 44 Ramos, Ramonita | stairs - cracked | stairs | City |
| 9/6/2022 | 35 | 102 Alvarez, Sara | baseboard, not secured | living room | City |
| 7/5/2022 | 35 | 102 Alvarez, Sara | bathtub unsealed | bathroom | City |
| 9/6/2022 | 35 | 102 Alvarez, Sara | cracks | dining room | City |
| 9/8/2022 | 35 | 102 Alvarez, Sara | fan, inoperable | bathroom | LLHD |
| 9/6/2022 | 35 | 102 Alvarez, Sara | fan, not working | bathroom | City |
| 7/5/2022 | 35 | 102 Alvarez, Sara | fan, not working | bathroom | City |
| 7/5/2022 | 35 | 102 Alvarez, Sara | floor buckling | living room | City |
| 9/8/2022 | 35 | 102 Alvarez, Sara | humidity, above 60% | bathroom | LLHD |
| 7/5/2022 | 35 | 102 Alvarez, Sara | leak, plumbing possible | dining room | City |
| 7/5/2022 | 35 | 102 Alvarez, Sara | moisture, basement | basement | City |
| 9/8/2022 | 35 | 102 Alvarez, Sara | mold | bathroom | LLHD |
| 7/5/2022 | 35 | 102 Alvarez, Sara | mold | bathroom | City |
| 9/6/2022 | 35 | 102 Alvarez, Sara | nail on railing | basement | City |
| 7/5/2022 | 35 | 102 Alvarez, Sara | paint bubbling | dining room | City |
| 9/6/2022 | 35 | 102 Alvarez, Sara | peeling paint | dining room | City |
| 9/6/2022 | 35 | 102 Alvarez, Sara | peeling paint | basement | City |
| 9/6/2022 | 35 | 102 Alvarez, Sara | water infiltration - basement | basement | City |
| 7/5/2022 | 35 | 102 Alvarez, Sara | windows, do not close | basement | City |
| 9/6/2022 | 35 | 110 Rodriguez, Victoria | cracks - dining room | dining room | City |
| | 35 | 110 Rodriguez, Victoria | mold/environmental review pending | Unit | LLHD |
| 9/6/2022 | 35 | 110 Rodriguez, Victoria | peeling paint - bathroom | bathroom | City |
| 9/6/2022 | 35 | 110 Rodriguez, Victoria | peeling paint - bedroom | bedroom | City |
| 9/6/2022 | 35 | 110 Rodriguez, Victoria | peeling paint - hallway | hall | City |
| 9/6/2022 | 35 | 110 Rodriguez, Victoria | plumbing - sink drain-improper piping | kitchen | City |
| 9/6/2022 | 35 | 110 Rodriguez, Victoria | railing - loose | basement | City |
| 9/6/2022 | 35 | 110 Rodriguez, Victoria | sump pump discharge malpiped | basement | City |
| 9/6/2022 | 37 | 132 Rosario, Diana | banister- loose and split | stairs | City |
| 9/6/2022 | 37 | 132 Rosario, Diana | bathtub unsealed | bathroom | City |
| 9/6/2022 | 37 | 132 Rosario, Diana | dip in floor | entry, rear | City |
| 9/6/2022 | 37 | 132 Rosario, Diana | drywall separating - kitchen | kitchen | City |

Inspection Findings

| | | | | | |
|----------|----|-------------------------|-----------------------------------|-------------|------|
| 9/6/2022 | 37 | 132 Rosario, Diana | fan held by drywall screws | bathroom | City |
| | 37 | 132 Rosario, Diana | mold/environmental review pending | Unit | LLHD |
| 9/6/2022 | 37 | 132 Rosario, Diana | peeling paint | dining room | City |
| 9/6/2022 | 37 | 132 Rosario, Diana | peeling paint | bathroom | City |
| 9/6/2022 | 37 | 132 Rosario, Diana | receptacle, gaps around | Unit | City |
| 9/6/2022 | 37 | 132 Rosario, Diana | weather stripping | entry | City |
| 9/6/2022 | 37 | 144 Carrieri, Christina | bathtub unsealed | bathroom | City |
| | 37 | 144 Carrieri, Christina | mold/environmental review pending | Unit | LLHD |
| 9/6/2022 | 37 | 144 Carrieri, Christina | peeling paint | basement | City |
| 9/6/2022 | 37 | 144 Carrieri, Christina | spalled concrete | basement | City |
| 9/6/2022 | 37 | 144 Carrieri, Christina | water infiltration - basement | basement | City |
| 9/6/2022 | 38 | 154 McAfee, Jill | damaged gypsum board | basement | City |
| | 38 | 154 McAfee, Jill | mold/environmental review pending | Unit | LLHD |
| 9/6/2022 | 38 | 154 McAfee, Jill | railing | basement | City |
| 9/6/2022 | 38 | 154 McAfee, Jill | spalled concrete | basement | City |
| 9/6/2022 | 38 | 154 McAfee, Jill | water infiltration - basement | basement | City |
| 9/6/2022 | 41 | 204 Wright, Joanne | leak detector going off | basement | City |
| | 41 | 204 Wright, Joanne | mold/environmental review pending | Unit | LLHD |
| 9/6/2022 | 41 | 204 Wright, Joanne | peeling paint | bathroom | City |
| 9/6/2022 | 41 | 204 Wright, Joanne | plumbing - improper support | Unit | City |
| 9/6/2022 | 42 | 222 Leary, Louann | chip in bathtub | bathroom | City |
| 9/6/2022 | 42 | 222 Leary, Louann | floor buckling | bedroom | City |
| | 42 | 222 Leary, Louann | mold/environmental review pending | Unit | LLHD |
| 9/6/2022 | 42 | 222 Leary, Louann | nail pops, ceiling | bedroom | City |
| 9/6/2022 | 42 | 222 Leary, Louann | peeling paint | bedroom | City |
| 9/6/2022 | 42 | 222 Leary, Louann | peeling paint | bathroom | City |
| 9/6/2022 | 42 | 224 Gibbs, Londa | baseboard, damaged | Unit | City |
| 9/6/2022 | 42 | 224 Gibbs, Londa | fan, dirty | bathroom | City |
| 9/6/2022 | 42 | 224 Gibbs, Londa | handrail - loose | stairs | City |
| | 42 | 224 Gibbs, Londa | mold/environmental review pending | Unit | LLHD |
| 9/6/2022 | 42 | 224 Gibbs, Londa | peeling paint | hallway | City |
| 9/6/2022 | 42 | 224 Gibbs, Londa | peeling paint | bedroom | City |
| 9/6/2022 | 43 | 254 Buraige, Latasha | door, cracked | bathroom | City |
| 9/6/2022 | 43 | 254 Buraige, Latasha | fan, slow to run | bathroom | City |
| | 43 | 254 Buraige, Latasha | mold/environmental review pending | Unit | LLHD |
| 9/6/2022 | 43 | 254 Buraige, Latasha | peeling paint | bedroom | City |
| 9/6/2022 | 43 | 254 Buraige, Latasha | peeling paint, paint bubbles | living room | City |
| 9/6/2022 | 43 | 254 Buraige, Latasha | rat droppings | Unit | City |

Inspection Findings

| | | | | | |
|----------|----|---------------------------|-------------------------------------|-------------|------|
| 9/6/2022 | 43 | 254 Buraage, Latasha | spalled concrete | basement | City |
| 9/6/2022 | 44 | 268 Santos, Christine | baseboard, taped | Unit | City |
| 9/6/2022 | 44 | 268 Santos, Christine | leak detector, not working | basement | City |
| | 44 | 268 Santos, Christine | mold/environmental review pending | Unit | LLHD |
| 9/6/2022 | 44 | 268 Santos, Christine | peeling paint | living room | City |
| 9/6/2022 | 44 | 268 Santos, Christine | peeling paint | hall | City |
| 9/6/2022 | 44 | 268 Santos, Christine | peeling paint, bathroom | bathroom | City |
| 9/6/2022 | 44 | 268 Santos, Christine | peeling paint, ceiling | kitchen | City |
| 9/6/2022 | 44 | 268 Santos, Christine | peeling paint, ceiling | dining room | City |
| 9/6/2022 | 44 | 268 Santos, Christine | peeling paint, nail pops | bedroom | City |
| 9/6/2022 | 44 | 268 Santos, Christine | water infiltration - basement | basement | City |
| 9/6/2022 | 44 | 270 Ortiz, Minerva | baseboard, damaged | Unit | City |
| 9/6/2022 | 44 | 270 Ortiz, Minerva | cracks | bedroom | City |
| 9/6/2022 | 44 | 270 Ortiz, Minerva | door, cracked | closet | City |
| 9/6/2022 | 44 | 270 Ortiz, Minerva | fan, dirty | bathroom | City |
| | 44 | 270 Ortiz, Minerva | mold/environmental review pending | Unit | LLHD |
| 9/6/2022 | 44 | 270 Ortiz, Minerva | paint bubbling | bathroom | City |
| 9/6/2022 | 44 | 270 Ortiz, Minerva | peeling paint | basement | City |
| 9/6/2022 | 44 | 270 Ortiz, Minerva | water infiltration - basement | basement | City |
| 9/6/2022 | 45 | 278 Diaz-Delgado, Yovelyn | drywall separating | bathroom | City |
| 9/6/2022 | 45 | 278 Diaz-Delgado, Yovelyn | electrical receptacle | bedroom | City |
| 9/6/2022 | 45 | 278 Diaz-Delgado, Yovelyn | fan, dirty | bathroom | City |
| 9/6/2022 | 45 | 278 Diaz-Delgado, Yovelyn | leak detector, not working properly | basement | City |
| | 45 | 278 Diaz-Delgado, Yovelyn | mold/environmental review pending | Unit | LLHD |
| 9/6/2022 | 45 | 278 Diaz-Delgado, Yovelyn | peeling paint | kitchen | City |
| 9/6/2022 | 45 | 278 Diaz-Delgado, Yovelyn | peeling paint | hall | City |
| 9/6/2022 | 45 | 278 Diaz-Delgado, Yovelyn | peeling paint | dining room | City |
| 9/6/2022 | 45 | 278 Diaz-Delgado, Yovelyn | window springs, broken | bathroom | City |
| | | | | | |
| | | | | | |