



**Statement of Evidence:**

The corner was originally established during the public land survey which was completed in 1854.

A survey made by C.J. Montgomery, dated August, 1894, in County Surveyor's Book C, page 25, indicates he identified the corner from a previous survey.

A survey made by George E. Sawyer, dated August, 1896, in County Surveyor's Book C, page 98, indicates he set a 19" x 17" x 11" stone.

A survey made by George E. Sawyer, dated November, 1900, in County Surveyor's Book D, page 29 $\frac{1}{2}$ , indicates he identified the corner from previous survey.

A survey made by Sawyer, dated October, 1901, in County Surveyor's Book D, page 55, indicates he identified the corner from previous survey in Book C, page 98.

The Martin County Highway Department describes the corner as having no records, then placed a 1" I.P. (2" deep), R.R. spike at surface.

The remaining ties are as follows:

50.0 E. = steel R.P. post

73.4 N.E. = power pole

75.0 S.E. = steel R.P. post

On 12/29/80, I found a 5/8" steel rod at surface.