

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Silver Lake

East 1/4 Corner of Section 12, Township T101N, Range R30W, 5th P.M.STATE OF MINNESOTA, County of MARTIN

At the corner location shown on the sketch:

- On 4-6-99 found a 3/4" I.P. (18" Deep)
DATE
- left monument as found, lowered monument, removed monument (explain)
- On _____ Placed a _____
DATE

SKETCH OF REFERENCE TIES



In Plowed Field

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE _____

DATE _____

Registration No. _____

- Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS
County of MARTIN

I hereby certify that this document was filed in the Reg. of Deeds office at _____M. on the

____ day of _____ A.D., 19____

Register of Deeds _____

By _____, Deputy

DOCUMENT NO. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 12, Township 101 N., Range 30 W., 5th P.M.

STATE OF MINNESOTA, County of MARTIN

At the corner location shown on the sketch:

- On 7/16/91 found an IRON ROD WITH PLASTIC CAP STAMPED RLS #12967
DATE DOWN 1.2'
- left monument as found, lowered monument, removed monument (explain)
- On _____ Placed a _____
DATE

SKETCH OF REFERENCE TIES



NOTE:
NO TIES AVAILABLE

CULTIVATED

FIELD

1983 MARTIN COUNTY
COORDINATE SYSTEM

N = 124049.738
E = 389258.307

Statement of evidence relative to this corner location is on back of page. 9/3/91
WMA00330.00.00.01

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision

Bruce W. Sheppard 9-20-91
SIGNATURE DATE

Registration No. 17003

Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER
County of _____

I hereby certify that this document was filed in the Co. recorders office at _____ .M. on the _____ day of _____ A.D., 19____

County Recorder _____
By _____, Deputy
DOCUMENT NO. _____

The DNR Bureau of Engineering contacted the following for survey information:

Minnesota Secretary of State's Office
Martin County Recorder's Office
Martin County Highway Engineer's Office
Madsen Land Surveying of Fairmont
Bolton and Menk, Inc., of Fairmont

- 1854 U.S. General Land Office notes obtained from the Secretary of State's Office's Office show the corner marked with a wood post and a charred stake in a mound of earth and sod with trench and pits. Also, planted apple seeds north and osage orange seeds south.
- 1878 May, Survey Number 5 on page 2 in Surveyor's Record Book A obtained from the County Recorder's Office contains a survey by D. P. Munger, County Surveyor. Survey states that corner was established by using the section corner to the south and the witness corner to the section corner to the north. A post in a mound with four pits were established to mark corner. No distances to corner are shown.

This information is also contained on pages 8 and 9 in East Chain Field Book 1 obtained from the County Recorder's Office.

- 1895 May, Survey Number 103 on page 49 in Surveyor's Record Book C obtained from the County Recorder's Office contains a survey by George E. Sawyer, Deputy County Surveyor. Survey shows that a small deep root and three pit marks agreeing with it but slightly oblique to line north, south and west was found at corner. Crockery to a depth of 28" with a 15" by 14" by 10" hardhead with a "+" and "1/4" 8" below the surface were set to mark corner. The corner is shown:
39.27 chains (2591.82') from the northeast corner of Section 12
50.06 chains (3303.96') from the witness corner to the northeast corner of Section 12
- 1896 June, Survey Number 183 on page 89 in Surveyor's Record Book C obtained from the County Recorder's Office contains a survey by George E. Sawyer, Deputy County Surveyor. Sawyer notes that all corners on Survey Number 8 on page 3 in Surveyor's Record Book A have disappeared except the witness corner to the northeast corner of Section 13. Survey shows that corner was identified per Survey Number 103 on page 49 in Surveyor's Record Book C. The corner is shown:
79.956 chains (5277.096') from the east quarter corner of Section 7
39.992 chains (2639.472') from a stone set for the center of Sec. 7
20.064 chains (1324.224') from a stone set for the east sixteenth corner of the southeast quarter of Section 12
- 1943 July, Survey Number 19 on page 87 in Surveyor's Record Book H obtained from the County Recorder's Office contains a survey by Frank O. Jones, County Surveyor. Survey states that a stone with a "+" on top was found at corner. The corner is shown:
under a fence
187.04 feet north of a stone with a "+" on top

- 1956 August, Survey Number 928 in Surveyor's Record Book J obtained from the County Recorder's Office contains a survey by Frank O. Jones, County Surveyor. Survey states that the stone per Survey Number 43 on page 49 in Surveyor's Record Book C is gone but were able to identify the crockery. A light gray 15" by 11" by 7" triangular shaped stone was laid flat down 8" over the crockery.
- 1959 July, DNR Bureau of Engineering established a position for corner using information obtained from Frank Jones, County Highway Engineer. A spike was set for corner and is shown:
in the center of a field
2590.0 feet from the northeast corner of Section 12
1302.5 feet from a stone with a "+" found at the east sixteenth corner of the northeast quarter of Section 12
- 1973 DNR Bureau of Engineering found a stone at the east sixteenth corner of the northeast quarter of Section 12. The stone was found to be:
3905.16 feet from the east quarter corner of Section 1
The east quarter corner of Section 12 was established as follows:
a) 1301.72 feet (3905.16/3) from the stone at the east sixteenth corner of the northeast quarter of Section 12
b) on the southerly extension of a line from the east quarter corner of Section 1 through the stone at the east sixteenth corner of the northeast quarter of Section 12
A monument was NOT set to mark the computed location of the corner.
- 1973 May, a page in a field notebook and a Certificate of Survey obtained from Bolton and Menk, Inc., shows that a stone with a "+" on top was found below plow depth at corner. A distance to corner is not given.
- 1981 April, a Certificate of Location of Government Corner signed by Gary D. Martin, RLS #12967, obtained from Madsen Land Surveying shows that a stone with a "+" on top was found 1.0 feet below the surface at corner. The stone was lowered to a depth of 3.5 feet and a 1/2" rebar with a plastic cap stamped "L.S. 12967" was set over it and the following ties were taken:
on the west edge of a north-south field road
5278.01 feet from the east quarter corner of Section 7
2639.33 feet from the center of Section 7
1304.03 feet from a stone found at the east sixteenth corner of the northeast quarter of Section 12
- This information is also contained on a page in a corner tie book obtained from the County Highway Engineer's Office.
- 1991 July, DNR Bureau of Engineering found an iron rod with a plastic cap stamped RLS #12967 down 1.2 feet in a cultivated field at corner. The iron rod was found to be:
5277.89 feet from the east quarter corner of Section 7
2590.66 feet from the northeast corner of Section 12
1304.38 feet from a stone found in the area of the east sixteenth corner of the northeast quarter of Section 12

Analysis of the above information led the DNR Bureau of Engineering to conclude that the found iron rod which was set over a stone in 1981 by Gary D. Martin marks the location of the corner as monumented by George E. Sawyer in 1895.