

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

LAKE BELT  
SOUTH 1/4

Corner of Section 36, Township 101N, Range 32W, 5th P.M.

STATE OF MINNESOTA, County of MARTIN


At the corner location shown on the sketch:

On 7-14-1994 found a STONE "+" - 6" DEEP - DRILLED HOLE IN STONE.  
DATE

left monument as found,  lowered monument,  removed monument (explain)

On 7-14-1994 Placed a 5/8" x 30" IRON ROD WITH ALUM. CAP 4" DEEP.  
DATE

## SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

\_\_\_\_\_  
SIGNATURE DATE

Registration No. \_\_\_\_\_

- Land Surveyor,  Professional Engineer
- County Surveyor,  County Engineer

OFFICE OF THE REGISTER OF DEEDS

County of \_\_\_\_\_

I hereby certify that this document was filed in the Reg. of Deeds office at

\_\_\_\_\_, M. on the

\_\_\_\_\_ day of \_\_\_\_\_, A.D., 19\_\_\_\_

Register of Deeds \_\_\_\_\_

By \_\_\_\_\_, Deputy

DOCUMENT NO. \_\_\_\_\_