

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Under corner on East Bank of Wilmont Lake on E.-W. $\frac{1}{4}$ Line *Silver Lake*
Corner of Section 7, Township 101N, Range 30W., 5th P.M.

STATE OF MINNESOTA, County of Martin


At the corner location shown on the sketch:

On 8/7/80 found a stone with "+" protruding 6"
DATE

left monument as found, lowered monument, removed monument (explain)

On 8/7/80 placed a 3/4" O.D. iron pipe on the east side of the stone
DATE
with "+".

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

John Maden 11-22-80
SIGNATURE DATE

Registration No. 13593

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER
County of Martin

I hereby certify that this document was filed in the Co. Recorders office at _____ M. on the _____ day of _____ A.D., 19 _____

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence:

The corner was established in a survey done by County Surveyor George E. Sawyer in November of 1892 and recorded in the Martin County Recorder's Office in Book B, page 196, identifies the corner as being a 10" x 10" x 16" stone with "+" protruding at 1.30 chains from shore of lake.

In a survey done in October of 1930, by George E. Sawyer and recorded in the County Recorder's Office in Book F, page 154 $\frac{1}{2}$, identifies the landmark as being 1.30 chains east of lake on quarter line protruding 8".

On 8/7/80, I found a 10" x 10" x 16" stone with "+" protruding 6" and placed a 3/4" O.D. iron pipe on the east side of stone with "+".